

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X		MRB Daily inspection AD (Performed by pilot/preflight)	FAA AD 2014-23-16																		
X	0.ANN	Perform Annual inspection as per RHC R22 MM §2.400 and Lycoming OM, and CAA/LAMP/H/2007 Issue 1, Section 6									12 MO	16-8-2018	16-8-2019	4							
X	912	First Aid Kit Inspection i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									12 MO	16-8-2018	16-8-2019	4							
X	901	ARC extension									12 MO	20-6-2018	20-6-2019	2							
X	903	Transponder Inspection i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									12 MO	9-12-2018	9-12-2019	8							
X	1.101-19	Inspect ELT per 14 CFR §91.207.																			
X	1.101-20	Test and inspection transponder per 14 CFR §91.413.																			
X	1.101-21	Perform 12 year maintenance and inspection per RHC R22 MM §2.600									144 MO	1-7-2010	1-7-2022								
X	3.300-09	P/N A158-3: [N/A] Main Rotor Spindle. Replace with new [Airworthiness limitation]					2200:00														
X	xxx	Engine cooling system panels - Pn: A027-4, A305-x, A306-1 & -2, A308-1, A309-1 or -15, A310-1 & -2, A312-1, A313-1 & A449-1. Renew at 2200hr.					2200:00														
X	xxx	Aft cross tube - Pn: A241-2. Renew at 2200hr.					2200:00														
X	902	Radio Annual Inspection i.a.w. CAA/LAMP/H/2007 Issue 1, Section 6									12 MO	9-12-2018	9-12-2019	8							
X	905	Radio Additional Inspections i.a.w. CAA/LAMP/H/2007 Issue 1, Section 6									36 MO	25-11-2016	25-11-2019	7							
X	906	Inspection & Calibration Altimeter i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									12 MO	9-12-2018	9-12-2019	8							
X	907	Inspection Pitot Static, Sense and Leak i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									12 MO	9-12-2018	9-12-2019	8							
X	908	Airspeed Indicator Calibration i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									12 MO	9-12-2018	9-12-2019	8							
X	909	Manifold Pressure Gauge calibration i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6																			
X	910	Magnetic Compass Compensation & Deviation Table i.a.w. CAA/LAMP/H/2007, Issue 1, Section 6									36 MO	25-11-2016	25-11-2019	7							
X	911	Fire Extinguisher Inspection i.a.w. CAA/LAMP/H/2007									12 MO	16-8-2018	16-8-2019	4							
X	913	Flexible Hoses Pressure Check i.a.w. CAP562: CAAI & P Book 2 Leaflet 20-50									36 MO	25-11-2016	25-11-2019	7							
X	914	Weight & Balance non-commercial									120 MO	28-4-2014	28-4-2024	60							
X	915	CAP 767 - check due items																			
X	900	UK - REQUIREMENTS I.A.W. CAA/LAMP/H/2007 Issue 1									12 MO	20-6-2018	20-6-2019	2							
X	MOD02	Inspect according to ICA-GTR225(x) paragraph 5 and test system in accordance with garmin installation manual 190-01182-02	GAMA CS-1447 / ICA-GTR225								12 MO	9-12-2018	9-12-2019	8							
X	1.102-02	P/N A005-12: [N/A] B370-1 Main Rotor Hub & Bearing Assembly. Perform inspection and repair per MM §2.610. Return to RHC for inspection and repair, or replace with new.					2200:00				144 MO	1-1-1900	1-1-1912								
X	1.102-04	P/N A005-7: [N/A] A016-6 MRB & A158-1 Spinde Assy. Replace with new or overhaul exchange A005-7 or A005-14 MRB and spindle assy																			
X	1.102-05	P/N A005-14: [N/A] A016-6 MRB & A158-3 Spinde Assy. Replace with new or overhaul exchange A005-7 or A005-14 MRB and spindle assy																			
X	1.102-09	P/N A014-8: [N/A] Landing Gear Assy originally installed on S/N 0002-0487 . Replace with new																			
X	1.102-12	P/N A020-2: [N/A] Upper frame assembly prior S/N 0399. Replace with new																			
X	1.102-13	P/N A021-1: [N/A] Tail rotor gearbox assembly. Replace with new or overhaul exchange B021-1																			

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X	1.102-15	P/N A041-11/A041-12: [N/A] Tail rotor drive shaft damper bearing assy. Replace with new or overhaul exchange B224-1/B224-3																			
X	1.102-16	P/N A044-1: [N/A] Horizontal stabiliser Rev M and prior. Replace with new		A044-1 REV U																	
X	1.102-20	P/N A169-1/A169-2/A169-4: [N/A] Muffler with riser originally installed on R22 S/N 0002-0500. Replace with new																			
X	1.102-22	P/N A169-24/A169-37: [N/A] Muffler with riser. Replace with new A169-37																			
X	1.102-25	P/N A193-2: [N/A] Flex plate. Replace with new A947-2																			
X	1.102-26	P/N A193-3: [N/A] Flex plate. Replace with new A947-3																			
X	1.102-27	P/N A197-#: [N/A] Tail rotor drive shaft assy originally installed R22 S/N 0002-0747. Replace with new B224-1 drive shaft & B223 Yoke																			
X	1.102-29	P/N A258-5: [N/A] MR pitch link assy. Disassemble, perform barrel fluorescent penetrant inspection.																			
X	1.102-32	P/N A493-1: [N/A] Lower Sheave originally installed R22 S/N 0002-0294. Replace with new																			
X	1.102-36	P/N A649-1/A649-2: [N/A] Oil cooler. Replace with new or overhaul exchange C649-1																			
X	1.102-53	P/N B224-1: [N/A] Tail rotor drive shaft . Replace with new					2200:00														
X	1.102-60	P/N C636-2: [N/A] Engine support. Replace with new					2200:00														
X	3.300-01	P/N A016-2: [N/A] Main rotor blade. Replace with new [Airworthiness limitation]					1964:00				120 MO										
X	3.300-06	P/N A016-6: [N/A] Main rotor blade. Replace with new [Airworthiness limitation]					2200:00				144 MO										
X	3.300-17	P/N A020-2: [N/A] Upper frame rev R and prior. Replace with new [Airworthiness limitation]					3750:00														
X	3.300-20	P/N A020-84: [N/A] Lower RH frame. Replace with new [Airworthiness limitation]					4400:00														
X	3.300-23	P/N A047-1/A047-6: [N/A] Upper frame. Replace with new [Airworthiness limitation]					4400:00														
X	3.300-26	P/N A030-1: [N/A] Tail rotor hub assembly. Replace with new [Airworthiness limitation]					5589:00														
X	3.300-25	P/N B370-1: [N/A] Main rotor hub. Replace with new [Airworthiness limitation]					4400:00														
X	1.101-11	[N/A] Lubricate A181-4 Rev K,L,M bearings per RHC R22 MM §22-42.																			
X	1.101-14	Perfrom Clutch assembly lubricant inspection and servicing per §22-30					500:00	6029:48	-5529:48	500:00											
X	1.102-08	P/N A008-4: Tail rotor Assembly. Replace with new A008-4					2200:00	6029:48	-3829:48	2200:00	144 MO	1-1-1900	1-1-1912	-1 28 7							
X	1.102-23	P/N A189-10: Double locking nut (1 or 3 ea). Replace with new					2200:00	6029:48	-3829:48	2200:00	144 MO	1-1-1900	1-1-1912	-1 28 7							
X	1.102-30	P/N A426-6: Collective spring cap. Replace with new					2200:00	6029:48	-3829:48	2200:00											
X	1.102-33	P/N A615-1: Gasket carburetor to airbox . Replace with new					2200:00	6029:48	-3829:48	2200:00											
X	1.102-59	P/N B350-2: Fanshaft nut spring pin. Replace with new					2200:00	6029:48	-3829:48	2200:00											
X	1.101-08	Change oil and oil filter, and check screen	LYC S.B. 480F				50:00	24:18	25:42	6055:30	4 MO	9-12-2018	9-4-2019	0							
X	MOD01	Check emergency landing light for security and cracks (MOD 95001)					50:00	24:18	25:42	6055:30	12 MO	9-12-2018	9-12-2019	8							
X	0.50H	Perform 50hrs inspection i.a.w. LAMP CAP 767, Lycoming OM.					50:00	24:18	25:42	6055:30	6 MO	9-12-2018	9-6-2019	2							
X	1.101-04	Check maintenance items	LYC S.L. 1080C				50:00	24:18	25:42	6055:30	12 MO	9-12-2018	9-12-2019	8							

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X	1.101-06	Perform carburetor throttle body screw inspection	LYC S.B. 366C				50:00	24:18	25:42	6055:30	12 MO	9-12-2018	9-12-2019	8							
X	SB103A	Perform main rotor blade bond inspection i.a.w. FAA AD 2014-23-16 & RHC R22 SB103A.	FAA AD 2014-23-16				100:00	24:18	75:42	6105:30	12 MO	9-12-2018	9-12-2019	8							
X	0.100H	Perform 100 hrs inspection i.a.w. LAMP CAP 767, RHC R22 MM §2.400 and Lycoming OM.					100:00	24:18	75:42	6105:30											
X	SL62a	Inspect and Clean B771-1 Air filter	RHC SL-62	B771-1			100:00	24:18	75:42	6105:30	12 MO	9-12-2018	9-12-2019	8							
X	SL55	Perform tap test on outboard doubler tips of MR blades with Pn: A016-4 i.a.w. RHC R22 SL55.	RHC SL-55	A016-4			100:00	24:18	75:42	6105:30	12 MO	9-12-2018	9-12-2019	8							
X	1.101-02	Check alternator/generator belt tension	LYC S.L. 1129D				100:00	24:18	75:42	6105:30											
X	1.101-03	Check cylinder compression	LYC S.L. 1191A				100:00	24:18	75:42	6105:30	12 MO	9-12-2018	9-12-2019	8							
X	1.101-09	Perform 100hrs magneto, ignition, sparkplug and harnesses inspection i.a.w. TCM SB643C.	TCM SB643C				100:00	24:18	75:42	6105:30	12 MO	9-12-2018	9-12-2019	8							
X	1.101-09a	Perform SB-183A Lycoming (magneto to engine timing)					100:00	24:18	75:42	6105:30											
X	1.101-05	Perform 300hrs exhaust valve and guide inspection i.a.w. Lycoming SB388C, SB301B and OM.	EASA AD 2005-0023R3 ; LYCOMING SB388C, SB301B				300:00	219:18	80:42	6110:30											
X	1.102-14	P/N A031-1: Tail rotor pitch control. Replace with new		A031-1	4326		2200:00	2104:00	96:00	6125:48	144 MO	30-8-2007	30-8-2019	4							
X	1.102-01	P/N A005-4: A154-1 Main Rotor Hub & Bearing Assembly. Perform inspection and repair per MM §2.610. Return to RHC for inspection and repair, or replace with new.					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-54	P/N B224-3: Tail rotor drive shaft. Replace with new		B224-3	6705		2200:00	2104:00	96:00	6125:48											
X	1.102-58	P/N B286-2: Governor controller. Replace with new or overhaul exchange		B286-2	1905		2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-07	P/N A007-5: Fanshaft Assembly. Replace with new A007-5 Fanshaft Assembly		A007-5	6783		2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-10	P/N A017-2: Swashplate assembly. Submit to RHC for overhaul, replace with new or overhaul exchange.		A017-2	2200		2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-17	P/N A051-1: Clutch actuator assembly. Replace with new or overhaul exchange		A051-1	1886		2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	3.300-08	P/N A146-1: main rotor gear box pinion. Replace with new [Airworthiness limitation]		A146-1	6800		2200:00	2104:00	96:00	6125:48											
X	1.101-18	Overhaul/Inspect 12 year inspection helicopter per RHC R22 MM §2.600					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	3.300-11	P/N A647-1: Bearing, main rotor shaft. Replace with new [Airworthiness limitation]					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-04a	P/N A181-4 PART OF ASSY A007-5: Lower sheave bearing					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-52	P/N B174-1: Fanwheel assembly (Rev J and subsequent). Replace with new or overhaul exchange					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-62	P/N D756-2: Throttle arm assembly. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	3.300-12	P/N A647-6: Bearing, tail rotor pitch control. Replace with new [Airworthiness limitation]					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-18	P/N A120-1: Tail Rotor Bellcrank . Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-19	P/N A121-17: Tail rotor push-pull tube assembly. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-24	P/N A190-1/190-2: V-belt set. Replace with new A190-2					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X	1.102-28	P/N A258-1: MR pitch link assemblies. Replace with new A258-5					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-31	P/N A480-1: Swashplate Boot. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-34	P/N A628-6: Harness assy. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-40	P/N A785-1: Hose air intake. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-46	P/N A792-2/A792-4: Dual tachometer . Replace with new or overhaul exchange A792-4					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	3.300-13	P/N A647-8: Bearing, damper assy. Replace with new [Airworthiness limitation]					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-55	P/N B283-1: Hose assy - fuel system. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-51	P/N B173-1: V-belt alternator. Replace with new (3VX375)					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-21	P/N A169-6/A169-35: Muffler with riser. Replace with new A169-35					2200:00	2104:00	96:00	6125:48											
X	1.102-35	P/N A636-2: Engine support. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-37	P/N A723-1: Replace with new A723-5					2200:00	2104:00	96:00	6125:48											
X	1.102-39	P/N A780-33: Battery cable. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-47	P/N A947-1: Flex plate assembly Forward. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-48	P/N A947-2: Flex plate assembly intermediate . Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-49	P/N A947-3: Flex plate assembly aft. Replace with new					2200:00	2104:00	96:00	6125:48											
X	1.102-64	P/N KI-217-1: Bladder fuel tank installation i.a.w. SB-109A (KIT KI-217-1)					2200:00	2104:00	96:00	6125:48	144 MO	15-1-2008	15-1-2020	9							
X	1.102-63	P/N F628-8: Harness Buckle. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-1-1900	1-1-1912	-1 28 7							
X	1.102-38	P/N A723-2: Replace with new A723-6					2200:00	2104:00	96:00	6125:48											
X	1.102-41	P/N A785-2: Hose air hot inlet. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-42	P/N A785-6: Hose engine cooling . Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-43	P/N A785-7: Hose alternator cooling. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-44	P/N A785-26: Hose air hot inlet . Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-45	P/N A785-32: Hose . Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-56	P/N B283-2: Hose assy - fuel system. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.102-57	P/N B283-6: Hose assy - fuel system. Replace with new					2200:00	2104:00	96:00	6125:48	144 MO	1-7-2010	1-7-2022	39							
X	1.101-12	Lubricate A181-4 Rev N lower bearing per RHC R22 MM §22-42.					800:00	675:48	124:12	6154:00	48 MO	20-5-2015	20-5-2019	1							
X	3.300-02a	P/N A016-4: Main rotor blade. Replace with new A016-6 [Airworthiness limitation] (FAA AD 2014-23-16)		A016-4	6067A		1964:00	1834:24	129:36	6159:24	144 MO	13-3-2007	13-3-2019	-1							
X	3.300-02b	P/N A016-4: Main rotor blade. Replace with new A016-6 [Airworthiness limitation] (FAA AD 2014-23-16)		A016-4	6203A		1964:00	1834:24	129:36	6159:24	144 MO	13-3-2007	13-3-2019	-1							
X	1.101-13	Lubricate A184 upper bearing per RHC R22 MM §22-41.	RHC SB-89				300:00	24:18	275:42	6305:30	12 MO	9-12-2018	9-12-2019	8							

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X	1.101-09bl	Perform LH airframe/RH engine magneto 500hrs inspection i.a.w. TCM SB643C, including SB658 and SB663A. (SB SB670 to be performed during 500HRS/Overhaul)	TCM SB643C				500:00	219:18	280:42	6310:30	48 MO	1-3-2018	1-3-2022	35							
X	1.101-09br	Perform RH airframe/LH engine magneto 500hrs inspection i.a.w. TCM SB643B, including SB658 and SB663A. (SB SB670 to be performed during 500HRS/Overhaul)	TCM SB643C				500:00	219:18	280:42	6310:30	48 MO	1-3-2018	1-3-2022	35							
X	1.101-15a	Drain and flush Main Rotor Gearbox per RHC R22 MM §22-13					500:00	219:18	280:42	6310:30											
X	1.101-15b	Drain and flush Tail Rotor Gearbox per RHC R22 MM §22-23					500:00	219:18	280:42	6310:30											
X	3.300-18	P/N A154-1: Main rotor hub assembly. Replace with new [Airworthiness limitation]		A154-1	5052		3928:00	3636:36	291:24	6321:12											
X	3.300-19	P/N A020-2: Upper frame revision S and subsequent. Replace with new [Airworthiness limitation]		A020-2 REV. AG	4418		4400:00	4056:06	343:54	6373:42											
X	3.300-21	P/N A023-23: Tailcone assembly. Replace with new [Airworthiness limitation]		A023-23	3732		4400:00	4056:06	343:54	6373:42											
X	1.101-17	FAA AD 88-26-01R2 Perform A158-1 main rotor spindle and A106 journals inspection	FAA AD 88-26-01 R2				500:00	124:24	375:36	6405:24											
X	1.101-16	Clean both gearbox chip detectors per RHC R22 MM §22-11 & 22-21. (Use solvent and brush i.a.w. manual)					500:00	124:24	375:36	6405:24	12 MO	16-8-2018	16-8-2019	4							
X	SL62b	Replace B771-1 Air filter	RHC SL-62	B771-1			600:00	74:18	525:42	6555:30	60 MO	24-10-2018	24-10-2023	54							
X	E02	Renew or overhaul starter	ICA BC315 MODEL STARTERS	BC315-11-2	1211121241		2000:00	1430:06	569:54	6599:42											
X	1.102-06	P/N A006-6: Main Rotor gearbox Assy. Replace with new or overhaul exchange A006-6 main rotor gearbox assembly		A006-6R	3100		2200:00	1372:54	827:06	6856:54	144 MO	27-6-2012	27-6-2024	62							
X	3.300-07a	P/N A029-2: Tail rotor blade. Replace with new [Airworthiness limitation]		A029-2	3381		2200:00	1309:36	890:24	6920:12	144 MO	15-11-2010	15-11-2022	43							
X	3.300-07b	P/N A029-2: Tail rotor blade. Replace with new [Airworthiness limitation]		A029-2	3380		2200:00	1309:36	890:24	6920:12	144 MO	15-11-2010	15-11-2022	43							
X	1.102-11	P/N A018-1/A018-2: Clutch assembly. Replace with new or overhaul exchange					2200:00	1192:48	1007:12	7037:00	144 MO	9-11-2012	9-11-2024	67							
X	1.102-11a	P/N A166-1 PART OF ASSY A018-1/A018-2: Clutch shaft. Replace with new or overhaul exchange.		A166-1	6892		2200:00	1192:48	1007:12	7037:00	144 MO	9-11-2012	9-11-2024	67							
X	3.300-10	P/N A188-2: Sprag clutch assembly. Replace with new [Airworthiness limitation]		A188-2	8762		2200:00	1192:48	1007:12	7037:00											
X	1.102-11b	P/N A184-3 PART OF ASSY A018-1/A018-2: Clutch bearing. Replace with new or overhaul		A184-3			2200:00	1192:48	1007:12	7037:00	144 MO	9-11-2012	9-11-2024	67							
X	1.102-50	P/N B021-1: Tail rotor gearbox assy. Replace with new or overhaul exchange		B021-1	2326		2200:00	1132:24	1067:36	7097:24	144 MO	1-3-2013	1-3-2025	71							
X	3.300-14	P/N B545-1: Tail rotor gear box, gear set. Replace with new [Airworthiness limitation]					2200:00	1132:24	1067:36	7097:24											
X	3.300-15	P/N B545-2: Tail rotor gear box, pinion. Replace with new [Airworthiness limitation]					2200:00	1132:24	1067:36	7097:24											
X	3.300-03	P/N NAS630-80/MS21250-10800: Coning Hinge Bolts. Replace with new [Airworthiness limitation]		NAS630-80	1409170791 .03		1964:00	675:48	1288:12	7318:00											
X	E01	Overhaul engine	LYC S.I. 1009BC	O-320-B2C	L-8154-39A		2000:00	675:48	1324:12	7354:00	144 MO	20-5-2015	20-5-2027	97							
X	E01a	Alternator	LYC S.I. 1009BC	ALY8520	H-00811152		2000:00	675:48	1324:12	7354:00	144 MO	20-5-2015	20-5-2027	97							
X	E01b	Renew or overhaul carburetor	LYC S.I. 1009BC	10-5217	DC42769		2000:00	675:48	1324:12	7354:00	144 MO	20-5-2015	20-5-2027	97							
X		Cylinder and head assemblies during engine overhaul i.a.w. Lycoming SB634					2000:00	675:48	1324:12	7354:00	144 MO	20-5-2015	20-5-2027	97							
X	1.102-03	P/N A005-6: A016-4 MRB & A158-1 Spinde Assy. Replace with new or overhaul exchange A005-7 or A005-14 MRB and spindle assy					2200:00	808:18	1391:42	7421:30	144 MO	13-3-2007	13-3-2019	-1							
X	3.300-05a	P/N A158-1: Main rotor spindle. Replace with new [Airworthiness limitation]		A158-1	21692		2156:00	675:48	1480:12	7510:00	144 MO	23-10-2014	23-10-2026	90							

## G-LAIN - Recurring Maintenance (All)

A/N	N Task No.	Description	AD Descr.	Pn	Sn	Ext.*	Int. FH	Item TT	Rem. FH	Due FH	Int. Cal.	Start Date	Due date	MO	Int. FC	FC LSV	Rem. FC	Due FC	Int. Cycl	m. Cycl	ue Cycl.
X	3.300-05b	P/N A158-1: Main rotor spindle. Replace with new [Airworthiness limitation]		A158-1	21690		2156:00	675:48	1480:12	7510:00	144 MO	23-10-2014	23-10-2026	90							
X	3.300-16	P/N NAS6604-24/NAS1304-24: Tail rotor blade to hub attach bolt. Replace with new [Airworthiness limitation]		NAS6604-24	35828-00		2200:00	675:48	1524:12	7554:00											
X	1.102-61	P/N C649-1: Oil cooler . Replace with new or overhaul exchange		C649-1	2969		2200:00	675:48	1524:12	7554:00	144 MO	20-5-2015	20-5-2027	97							
X	3.300-04	P/N NAS1351-4-20/A722-1/A722-2: Pitch horn screws. Replace with new [Airworthiness limitation]		NAS1351-4-20	LAIN3 ? (UIT OUDE CARDEX)		1964:00	219:18	1744:42	7774:30											
X	1.101-09cl	Perform LH airframe/RH engine magneto overhaul i.a.w. TCM SB643C, including SB658 and SB663A. (SB SB670 to be performed during 500HRS/Overhaul)	TCM SB643C	10-600644-201	J299804ER		2000:00	219:18	1780:42	7810:30	48 MO	1-3-2018	1-3-2022	35							
X	1.101-09cr	Perform RH airframe/LH engine magneto overhaul i.a.w. TCM SB643C, including SB658 and SB663A. (SB SB670 to be performed during 500HRS/Overhaul)	TCM SB643C	10-600614-1	I149802E		2000:00	219:18	1780:42	7810:30	48 MO	1-3-2018	1-3-2022	35							
X	3.300-22	P/N A046-2: Lower RH frame. Replace with new [Airworthiness limitation]		A046-2	5459		4400:00	2104:00	2296:00	8325:48											
X	3.300-24	P/N A062-2: Tail rotor hub (part of Assy A062-1). Replace with new [Airworthiness limitation]		A062-1	4358		4400:00	1309:36	3090:24	9120:12											