

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                     |               | Engine(s)       |             | 1        |            |            |            |      |                      |            |          |           |        |                                                      |
|--------------------------------------------------------------------------------------------------------------|---------------|-----------------|-------------|----------|------------|------------|------------|------|----------------------|------------|----------|-----------|--------|------------------------------------------------------|
| TT:                                                                                                          | 2776:20       | TSO:            | 1576:08     |          |            |            |            |      |                      |            |          |           |        |                                                      |
| Hobbs:                                                                                                       | 595:44        | Pn:             | O-540-F1B5  |          |            |            |            |      |                      |            |          |           |        |                                                      |
| Type:                                                                                                        | R44 RAVEN I   | Sn:             | L-21252-40E |          |            |            |            |      |                      |            |          |           |        |                                                      |
| Sn:                                                                                                          | 2073          |                 |             |          |            |            |            |      |                      |            |          |           |        |                                                      |
| Description                                                                                                  | AD/SB/MOD No. | ATA / Action Pn | Sn          | Curr. FH | Start date | Ac. TT LSV | tem TT LSV | TH   | Int.                 | Ext.*      | Open Ite | Appl. N/A | Due RT | Rem. RT                                              |
| EUROPEAN REQUIREMENTS                                                                                        |               | 000             |             |          | 2776:20    |            |            | 0:00 |                      |            |          |           | X      |                                                      |
| Full Airworthiness Review (controlled environment)                                                           |               | 001             | INSP        |          | 2776:20    | 25.02.2026 | 2753:01    |      | 36MO+0/-90DY         |            |          |           | X      | 16 Apr 2029+0/-90DY 1113+0/-90DY                     |
| ARC Extension                                                                                                |               | 002             | INSP        |          | 2776:20    | 16.04.2026 | 2753:01    |      | 12MO+0/-30DY         |            |          |           | X      | 16 Apr 2027+0/-30DY 382+0/-30DY                      |
| Check First Aid Kit for expired items. Replace if necessary and inform CA(M)O about new next due expiry date |               | 008             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    |      | 12MO                 | 15DY       | X        |           | X      | 05 Apr 2026+15DY* 21DY                               |
| Perform Weight & Balance (AMC1 CAT.POL.MAB.100(b)) and replace POH W&B Report & Equipmentlist                |               | 009             | INSP        |          | 2776:20    | 02.03.2023 |            | 0:00 | 48MO                 | 30DY       |          |           | X      | 02 Mar 2027+30DY* 367DY                              |
| AUSTRIAN REQUIREMENTS                                                                                        |               | 010             |             |          | 2776:20    |            |            | 0:00 |                      |            |          |           | X      |                                                      |
| Perform LTH 40A 4.1 - Avionic Inspection                                                                     |               | 011             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00 | 24MO                 | 30DY       |          |           | X      | 05 Mar 2027+30DY* 370DY                              |
| Perform LTH 40A 4.2 - Transponder Inspection                                                                 |               | 012             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00 | 24MO                 | 30DY       |          |           | X      | 05 Mar 2027+30DY* 370DY                              |
| Perform LTH 40A 4.3 - Pitot Static Check                                                                     |               | 013             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00 | 24MO                 | 30DY       |          |           | X      | 05 Mar 2027+30DY* 370DY                              |
| Perform LTH 40A 4.3 - Compass Compensation and replace deviation table in cockpit                            |               | 013             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00 | 24MO                 | 30DY       |          |           | X      | 05 Mar 2027+30DY* 370DY                              |
| Perform LTA 71A (d) - Special Inspection for piston engines older than 12 years                              |               | 016             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    |      | 156M O 72MO          |            |          |           | X      | 09 Apr 2031 1836DY                                   |
| Perform LTA 71A (b),(c),(e),(f),(g) - Special Inspection for piston engines older than 12 years              |               | 017             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    |      | 156M O 36MO          |            |          |           | X      | 09 Apr 2028 741DY                                    |
| SCHEDULED MAINTENANCE AIRFRAME RHC MM § 1.101                                                                |               | 100             | INSP        |          | 2776:20    |            |            | 0:00 |                      |            |          |           | X      |                                                      |
| RHC § 2.600 - Perform 2200-hour inspection (R44 / R44 II)                                                    |               | 101a            | INSP        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00 | 2200FH               | 50FH       |          |           | X      | 4380:36+50FH* 1654:16FH                              |
| RHC § 2.600 - Perform 12-Year inspection                                                                     |               | 102             | INSP        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00 | 144MO                | 30DY       |          |           | X      | 13 Mar 2035+30DY* 3300DY                             |
| RHC § 2.200 - Perform Ground & Flight Check for 100hour/Annual Inspection                                    |               | 103a            | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |
| RHC § 2.300 - Perform Airframe Preparation for 100-Hour/Annual Inspection                                    |               | 103b            | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |
| RHC § 2.400 - Perform 100-hour/Annual Airframe Inspection                                                    |               | 104             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |
| RHC § 7.210 - Perform clutch assembly lubricant inspection & servicing                                       |               | 105             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 500FH                | 25FH       |          |           | X      | 3180:36+25FH* 429:16FH                               |
| RHC § 1.120 - Drain and flush MGB                                                                            |               | 108             | INSP        |          | 2776:20    | 18.07.2025 | 2685:19    | 0:00 | 4FH 500FH            | 25FH       |          |           | X      | 3185:19+25FH* 433:59FH                               |
| RHC § 1.130 - Drain and flush TGB                                                                            |               | 109             | INSP        |          | 2776:20    | 18.07.2025 | 2685:19    | 0:00 | 4FH 500FH            | 25FH       |          |           | X      | 3185:19+25FH* 433:59FH                               |
| RHC § 1.115 - Clean gearbox chip detectors                                                                   |               | 110             | INSP        |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00 | 4FH 500FH / 12MO     | 15DY       | X        |           | X      | 3076:50FH / 05 Apr 2026+15DY* 300:30FH / 21DY        |
| RHC § 1.140 - Lubricate C181-3 bearings                                                                      |               | 111             | INSP        |          | 2776:20    | 14.06.2024 | 2480:36    | 0:00 | 300FH / 36MO         | 15FH/ 30DY | X        |           | X      | 2780:36+15FH* / 14 Jun 2027+30DY* 19:16FH / 471DY    |
| RHC § 1.140 - Perform Ground Run after bearing lubrication                                                   |               | 112             | INSP        |          | 2776:20    | 14.06.2024 | 2480:36    | 0:00 | 300FH / 36MO         | 15FH/ 30DY | X        |           | X      | 2780:36+15FH* / 14 Jun 2027+30DY* 19:16FH / 471DY    |
| RHC § 1.170 - Replace hydraulic filter                                                                       |               | 113             | INSP        |          | 2776:20    | 18.07.2025 | 2671:19    | 0:00 | 300FH                | 15FH       |          |           | X      | 2971:19+15FH* 209:59FH                               |
| RHC SL-38 - Perform Cracked MS2142L-Nuts Inspection                                                          |               | 122             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100±10FH / 12MO±15DY |            | X        |           | X      | 2780:36±10FH / 18 Jul 2026±15DY 4:16±10FH / 110±15DY |
| RHC SL-43 - Perform C343-1 Rev. L and prior Push-Pull Tube Inspection                                        |               | 123             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |
| RHC SL-46 - Clean Air Filter P/N B771-1/B771-2                                                               |               | 124             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |
| RHC SL-46 - Replace Air Filter P/N B771-1/B771-2                                                             |               | 125             | INSP        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00 | 600FH / 60MO         | 30FH/ 30DY | X        |           | X      | 2780:36+30FH* / 13 Mar 2028+30DY* 34:16FH / 744DY    |
| Reminder: D210 Corrosion-Resistant (CRES) Nuts                                                               | R44_SL-50A    | 126             | INSP        |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00 | 100FH / 12MO         | 10FH/ 15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* 14:16FH / 125DY    |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                                                                                                   |                                            | Engine(s)    |             | 1       |          |            |            |            |         |       |                      |           |          |           |        |                                   |                      |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|--------------|-------------|---------|----------|------------|------------|------------|---------|-------|----------------------|-----------|----------|-----------|--------|-----------------------------------|----------------------|
| TT:                                                                                                                                                                                        | 2776:20                                    | TSO:         | 1576:08     |         |          |            |            |            |         |       |                      |           |          |           |        |                                   |                      |
| Hobbs:                                                                                                                                                                                     | 595:44                                     | Pn:          | O-540-F1B5  |         |          |            |            |            |         |       |                      |           |          |           |        |                                   |                      |
| Type:                                                                                                                                                                                      | R44 RAVEN I                                | Sn:          | L-21252-40E |         |          |            |            |            |         |       |                      |           |          |           |        |                                   |                      |
| Sn:                                                                                                                                                                                        | 2073                                       |              |             |         |          |            |            |            |         |       |                      |           |          |           |        |                                   |                      |
| Description                                                                                                                                                                                | AD/SB/MOD No.                              | ATA / Action | Pn          | Sn      | Curr. FH | Start date | Ac. TT     | LSV tem    | TT LSV  | TH    | Int.                 | Ext.*     | Open Ite | Appl. N/A | Due RT | Rem. RT                           |                      |
| RHC SL-64A - Perform Fire Extinguisher Handling & Maintenance P/N B381- (RT-A400)                                                                                                          |                                            | 127          | INSP        |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100FH / 12MO         | 10FH/15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* | 14:16FH / 125DY      |
| RHC § 28-60 (RHC SL-70) - Perform Main Rotor Blade Tip Maintenance                                                                                                                         |                                            | 128          | INSP        |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100FH / 12MO         | 10FH/15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* | 14:16FH / 125DY      |
| Check Hook and Loop Style Fasteners as Mounting Mechanism for an Emergency Locator Transmitter                                                                                             | EASA_SIB_2013-04R2; KANNAD_SB_S180000 0-25 | 139          |             |         |          | 2776:20    | 09.04.2025 | 2576:50    |         |       | 12MO±15DY            |           | X        |           | X      | 09 Apr 2026±15DY                  | 10±15DY              |
| Perform Gear Motor (P/N D276-1 or D276-3) Assembly Torque Stripe Inspection                                                                                                                | FAA_SAIB_2024-05                           | 142          |             |         |          | 2776:20    | 18.07.2025 | 2671:19    | 0:00    |       | 100±10FH / 12MO±15DY |           | X        |           | X      | 2780:36±10FH / 18 Jul 2026±15DY   | 4:16±10FH / 110±15DY |
| Perform ELT Security                                                                                                                                                                       | FAA_SAIB_AIR-22-03; R44_SL-81              | 143          |             |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100±10FH / 12MO±15DY |           | X        |           | X      | 2780:36±10FH / 18 Jul 2026±15DY   | 4:16±10FH / 110±15DY |
| Perform Tail Rotor Blade Condition and Care                                                                                                                                                | R44_SL-82A                                 | 144          |             |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100±10FH / 12MO±15DY |           | X        |           | X      | 2780:36±10FH / 18 Jul 2026±15DY   | 4:16±10FH / 110±15DY |
| Critical Tasks: The Maintenance Organization has to follow the manufacturer instructions and regulations acc. Part-M/ML and Part-145.                                                      |                                            | 150          | INSP        |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100FH / 12MO         | 10FH/15DY | X        |           | X      | 2780:36+10FH* / 18 Jul 2026+15DY* | 14:16FH / 125DY      |
| MODIFICATIONS                                                                                                                                                                              |                                            | 179          |             |         |          | 2776:20    |            |            |         |       |                      |           |          |           | X      |                                   |                      |
| Perform GTR225A/B or GNC255A/B 12-Month Inspection acc. GAMA ICA-1447 ICA-GTR225(x) Issue 1, Chapter 5                                                                                     |                                            | 183          | INSP        |         |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00    |       | 12MO                 | 15DY      | X        |           | X      | 05 Apr 2026+15DY*                 | 21DY                 |
| Kannad AF-Compact - Perform 6 Years Inspection (together with Battery replacement) acc. Kannad SL S1840501-25-05, current revision                                                         |                                            | 186          | INSP        |         |          | 2776:20    | 30.09.2023 |            | 0:00    |       | 72MO                 |           |          |           | X      | 30 Sep 2029                       | 1280DY               |
| Kannad AF-Compact - Perform Annual Inspection acc. Kannad SL S1840501-25-05, current revision                                                                                              |                                            | 187          | INSP        |         |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00    |       | 12MO                 | 15DY      | X        |           | X      | 05 Apr 2026+15DY*                 | 21DY                 |
| Perform Battery Cap Check as long as the capacity is abouve 90% acc. Concorde CMM 24-30-71, Chapter "Testing and Fault Isolation", Item 1.B (Page 101). Please note capacity for next due. |                                            | 196          | INSP        | RG-25XC | 41461204 |            | 2776:20    | 13.09.2025 | 4877:44 |       | 12MO±15DY            |           |          |           | X      | 13 Sep 2026±15DY                  | 167±15DY             |
| Perform Battery Cleaning acc. Concorde CMM 24-30-71, Chapter "Cleaning" (Page 401)                                                                                                         |                                            | 197          | CLN         | RG-25XC | 41461204 |            | 2776:20    | 13.09.2025 | 4877:44 |       | 12MO±15DY            |           |          |           | X      | 13 Sep 2026±15DY                  | 167±15DY             |
| Perform Battery Check acc. Concord CMM 24-30-71, Chapter "Check" (Page 501)                                                                                                                |                                            | 197          | CHK         | RG-25XC | 41461204 |            | 2776:20    | 13.09.2025 | 4877:44 |       | 12MO±15DY            |           |          |           | X      | 13 Sep 2026±15DY                  | 167±15DY             |
| SCHEDULED MAINTENANCE ENGINE LYC OM § 04                                                                                                                                                   |                                            | 200          | INSP        |         |          | 2776:20    |            |            |         | 0:00  |                      |           |          |           | X      |                                   |                      |
| LYC § 04.4 - Perform 50-Hour Inspection                                                                                                                                                    |                                            | 204          | INSP        |         |          | 2776:20    | 05.11.2025 | 2728:22    | 0:00    |       | 50±5FH               |           | X        |           | X      | 2774:36±5FH                       | -1:44±5FH            |
| LYC § 04.5 - Perform 100-Hour Inspection                                                                                                                                                   |                                            | 205          | INSP        |         |          | 2776:20    | 18.07.2025 | 2671:19    | 0:00    |       | 100±10FH             |           | X        |           | X      | 2780:36±10FH                      | 4:16±10FH            |
| LYC § 04.6 - Perform 400-Hour Inspection (Shorter Intervall)                                                                                                                               |                                            | 206          | INSP        |         |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00    | 100FH | 300±30FH             |           |          |           | X      | 2880:36±30FH                      | 104:16±30FH          |
| Perform LYC SI-1129E - Method of checking DC Alternator Belt Tension                                                                                                                       |                                            | 207          | INSP        |         |          | 2776:20    | 18.07.2025 | 2671:19    | 0:00    | 25FH  | 100±10FH             |           | X        |           | X      | 2780:36±10FH                      | 4:16±10FH            |
| Perform LYC SI-1191A - Cylinder Compression                                                                                                                                                |                                            | 208          | INSP        |         |          | 2776:20    | 18.07.2025 | 2671:19    | 0:00    |       | 100±10FH             |           | X        |           | X      | 2780:36±10FH                      | 4:16±10FH            |
| LYC SI-1080D - Maintenance Items for special attention - Perform 50hrs Inspection acc. Table 1                                                                                             |                                            | 209          | INSP        |         |          | 2776:20    | 05.11.2025 | 2728:22    | 0:00    | 25FH  | 50±5FH               |           | X        |           | X      | 2774:36±5FH                       | -1:44±5FH            |
| LYC SI-1080D - Maintenance Items for special attention - Perform 100hrs/Annual Inspection acc. Table 1                                                                                     |                                            | 209          | INSP        |         |          | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |       | 100±10FH / 12MO±15DY |           | X        |           | X      | 2780:36±10FH / 18 Jul 2026±15DY   | 4:16±10FH / 110±15DY |
| Perform LYC SB-301B - Maintenance Procedure and Service Limitation for Valves                                                                                                              |                                            | 210          | INSP        |         |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00    | 100FH | 300±30FH             |           |          |           | X      | 2880:36±30FH                      | 104:16±30FH          |
| Perform LYC SB-366C - Carburetor Throttle Body Screw Inspection                                                                                                                            |                                            | 212          | INSP        |         |          | 2776:20    | 05.11.2025 | 2728:22    | 0:00    |       | 50±5FH               |           | X        |           | X      | 2774:36±5FH                       | -1:44±5FH            |
| Perform Exhaust Valve and Guide Condition                                                                                                                                                  | EU-2005-0023R3; HB-2006-330; LYC_SB-388C   | 213          |             |         |          | 2776:20    | 09.04.2025 | 2576:50    | 0:00    | 100FH | 330FH                |           |          |           | X      | 2906:50FH                         | 130:30FH             |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                                                                                                                         |               | Engine(s)    |             | 1             |                    |            |            |            |         |      |                   |            |          |           |                                   |                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--------------|-------------|---------------|--------------------|------------|------------|------------|---------|------|-------------------|------------|----------|-----------|-----------------------------------|---------------------|
| TT:                                                                                                                                                                                                              | 2776:20       | TSO:         | 1576:08     |               |                    |            |            |            |         |      |                   |            |          |           |                                   |                     |
| Hobbs:                                                                                                                                                                                                           | 595:44        | Pn:          | O-540-F1B5  |               |                    |            |            |            |         |      |                   |            |          |           |                                   |                     |
| Type:                                                                                                                                                                                                            | R44 RAVEN I   | Sn:          | L-21252-40E |               |                    |            |            |            |         |      |                   |            |          |           |                                   |                     |
| Sn:                                                                                                                                                                                                              | 2073          |              |             |               |                    |            |            |            |         |      |                   |            |          |           |                                   |                     |
| Description                                                                                                                                                                                                      | AD/SB/MOD No. | ATA / Action | Pn          | Sn            | Curr. FH           | Start date | Ac. TT     | LSV tem    | TT LSV  | TH   | Int.              | Ext.*      | Open Ite | Appl. N/A | Due RT                            | Rem. RT             |
| Perform LYC SB-480F - (and R44 SL-83, as applicable)<br>I. Oil & Filter Change & Screen Cleaning / II. Oil Filter/Screen Content<br>Inspection. NOTE: Oil filters on D723-1 adapters do not require safety wire. | LYC_MSB-480F  | 215          | INSP        |               |                    | 2776:20    | 05.11.2025 | 2728:22    | 0:00    | 25FH | 50±5FH / 4MO±15DY |            | X        | X         | 2776:50±5FH / 18 Mar 2026±15DY    | 0:30±5FH / -12±15DY |
| Perform LYC SB-183A - Magneto Timing Discrepancies                                                                                                                                                               |               | 216          | INSP        |               |                    | 2776:20    | 18.07.2025 | 2671:19    | 0:00    |      | 100±10FH          |            | X        | X         | 2780:36±10FH                      | 4:16±10FH           |
| Perform visual inspection of the engine oil filter, oil pressure screen, and oil suction screen (depending on the engine configuration) for bronze metal particulates acc. chapter (g)(1) thru (g)(3)            | US-2026-04-11 | 221          | INSP        |               |                    | 2776:20    | 05.11.2025 | 2728:22    | 0:00    |      | 50±5FH / 4MO±15DY |            | X        | X         | 2776:50±5FH / 18 Mar 2026±15DY    | 0:30±5FH / -12±15DY |
| SCHEDULED MAINTENANCE LH MAGNETO                                                                                                                                                                                 |               | 250          | INSP        |               |                    | 2776:20    |            |            | 0:00    |      |                   |            |          | X         |                                   |                     |
| CMI SB-643C - Perform LH Magneto 100 Hours/Annual Inspection                                                                                                                                                     |               | 252          | INSP        |               |                    | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |      | 100FH / 12MO      | 10FH       | X        | X         | 2780:36+10FH* / 18 Jul 2026       | 14:16FH / 110DY     |
| CMI SB-643C - Perform LH Magneto 500 Hours Inspection or replace                                                                                                                                                 |               | 254          | INSP        | 10-600616-3   | E09AA039           |            | 2776:20    | 18.07.2025 | 2671:19 | 0:00 | 500FH             | 25FH/ 30DY |          | X         | 3171:19+25FH* / 28 Mar 2027+30DY* | 419:59FH / 393DY    |
| Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - LH Magneto                                                                                                                          |               | 262          | INSP        |               |                    | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |      | 500FH / 60MO      | 25FH/ 30DY |          | X         | 3180:36+25FH* / 18 Jul 2030+30DY* | 429:16FH / 1601DY   |
| SCHEDULED MAINTENANCE RH MAGNETO                                                                                                                                                                                 |               | 280          |             |               |                    | 2776:20    |            |            | 0:00    |      |                   |            |          | X         |                                   |                     |
| CMI SB-643C - Perform RH Magneto 100 Hours/Annual Inspection                                                                                                                                                     |               | 282          | INSP        |               |                    | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |      | 100FH / 12MO      | 10FH       | X        | X         | 2780:36+10FH* / 18 Jul 2026       | 14:16FH / 110DY     |
| CMI SB-643C - Perform RH Magneto 500 Hours Inspection or replace                                                                                                                                                 |               | 284          | INSP        | 10-600646-201 | D06AA087R          |            | 2776:20    | 18.07.2025 | 2671:19 | 0:00 | 500FH             | 25FH/ 30DY |          | X         | 3171:19+25FH* / 28 Mar 2027+30DY* | 419:59FH / 393DY    |
| Perform CMI SB-663A Two-Wire Magneto Tach. Breaker Contact (Points) Assy. P/N 10-400507 - RH Magneto Model S4LSC-204T (P/N 10-600644-201, BL-600644-201) and S6LSC-204T (P/N 10-600646-201, BL-600646-201)       |               | 288          | INSP        | 10-600646-201 | D06AA087R          |            | 2776:20    | 18.07.2025 | 2671:19 | 0:00 | 500FH / 60MO      | 25FH/ 30DY |          | X         | 3171:19+25FH* / 18 Jul 2030+30DY* | 419:59FH / 1601DY   |
| Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - RH Magneto                                                                                                                          |               | 292          | INSP        |               |                    | 2776:20    | 18.07.2025 | 2680:36    | 0:00    |      | 500FH / 60MO      | 25FH/ 30DY |          | X         | 3180:36+25FH* / 18 Jul 2030+30DY* | 429:16FH / 1601DY   |
| FATIGUE LIFE-LIMITED PARTS RHC MM § 3.120                                                                                                                                                                        |               | 300          | LL          |               |                    | 2776:20    |            |            | 0:00    |      |                   |            |          | X         |                                   |                     |
| Main Rotor Blade, Rev. AK & Subsequent - Replace (Note: Whichever limit occurs first. Calendar time starts on date of original RHC-issued Airworthiness Approval)                                                |               | 305          | LL          | C016-7        | 15144/15141 REV.AK |            | 2776:20    | 07.11.2022 | 2180:36 | 0:00 | 2200FH / 180MO    |            |          | X         | 4380:36FH / 07 Nov 2037           | 1604:16FH / 4240DY  |
| Upper Frame - Replace                                                                                                                                                                                            |               | 308          | LL          | C020-1        | 11409 REV.X        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Tail Rotor Blade, Rev. R & Subsequent - Replace (Note: Whichever limit occurs first. Calendar time starts on date of original RHC-issued Airworthiness Approval)                                                 |               | 315          | LL          | C029-3        | 14708/14704 REV.R  |            | 2776:20    | 07.11.2022 | 2180:36 | 0:00 | 2200FH / 180MO    |            |          | X         | 4380:36FH / 07 Nov 2037           | 1604:16FH / 4240DY  |
| Pinion, Main Gearbox - Replace                                                                                                                                                                                   |               | 320          | LL          | C146-2        | R2252 REV.Q        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Main Rotor Hub - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                                 |               | 321          | LL          | C154-1        | 13103 REV.I        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Main Rotor Spindle - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                             |               | 322          | LL          | C158-1        | 29327 REV.M        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Main Rotor Spindle - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                             |               | 323          | LL          | C158-1        | 29328 REV.M        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Sump, Main Gearbox - Replace                                                                                                                                                                                     |               | 326          | LL          | C263-2        | 9702 REV.I         |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Housing, Main Gearbox - Replace                                                                                                                                                                                  |               | 328          | LL          | C264-2        | 12120 REV.L        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |
| Pinion, Tail Gearbox - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                           |               | 330          | LL          | C545-2        | 13684 REV.M        |            | 2776:20    | 13.03.2023 | 2180:36 | 0:00 | 2200FH            |            |          | X         | 4380:36FH                         | 1604:16FH           |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                                                                                                                                                                                                                         |               | Engine(s)    |             | 1       |          |            |         |            |         |      |                |       |          |           |                   |           |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--------------|-------------|---------|----------|------------|---------|------------|---------|------|----------------|-------|----------|-----------|-------------------|-----------|
| TT:                                                                                                                                                                                                                                                                                                              | 2776:20       | TSO:         | 1576:08     |         |          |            |         |            |         |      |                |       |          |           |                   |           |
| Hobbs:                                                                                                                                                                                                                                                                                                           | 595:44        | Pn:          | O-540-F1B5  |         |          |            |         |            |         |      |                |       |          |           |                   |           |
| Type:                                                                                                                                                                                                                                                                                                            | R44 RAVEN I   | Sn:          | L-21252-40E |         |          |            |         |            |         |      |                |       |          |           |                   |           |
| Sn:                                                                                                                                                                                                                                                                                                              | 2073          |              |             |         |          |            |         |            |         |      |                |       |          |           |                   |           |
| Description                                                                                                                                                                                                                                                                                                      | AD/SB/MOD No. | ATA / Action | Pn          | Sn      | Curr. FH | Start date | Ac. TT  | LSV tem    | TT LSV  | TH   | Int.           | Ext.* | Open Ite | Appl. N/A | Due RT            | Rem. RT   |
| Bearing Set, C017-6 Swashplate - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                                                                                                                 |               | 331          | LL          | C647-12 | 227774   | REV.AH     | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| Tail Rotor Guard - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                                                                                                                               |               | 333          | LL          | D079-1  | 13763    | REV.W      | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| Tail Rotor Hub - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                                                                                                                                 |               | 334          | LL          | G062-2  | 8132     |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| Tailcone Assembly, Rev N & Subsequ. - Replace                                                                                                                                                                                                                                                                    |               | 336          | LL          | C023-1  | 5801     | REV.AH     | 2776:20 | 26.04.2010 | 0:00    | 0:00 | 4400FH         |       |          | X         | 4400FH            | 1623:40FH |
| Horizontal Stabilizer, Rev. M & Subsequ. - Replace (Note: Maximum service life is 2000 hours if part is, or ever has been, installed on an R66 helicopter)                                                                                                                                                       |               | 342          | LL          | C044-1  | 10631    | REV.Z      | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 4400FH         |       |          | X         | 6580:36FH         | 3804:16FH |
| Lower Swashplate - Replace                                                                                                                                                                                                                                                                                       |               | 344          | LL          | C198-2  | 5951     |            | 2776:20 | 26.04.2010 | 0:00    | 0:00 | 4400FH         |       |          | X         | 4400FH            | 1623:40FH |
| Tail Rotor Drive Shaft                                                                                                                                                                                                                                                                                           |               | 349          | LL          | D196-1  | 10932    | REV.H      | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 4400FH         |       |          | X         | 6580:36FH         | 3804:16FH |
| ADDITIONAL COMPONENT MAINTENANCE RHC MM § 1.102                                                                                                                                                                                                                                                                  |               | 350          |             |         |          |            | 2776:20 |            |         |      |                |       |          | X         |                   |           |
| RHC § 1.102 A. Perform 12 Years Additional Component Maintenance                                                                                                                                                                                                                                                 |               | 350a         |             |         |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 144MO          | 30DY  |          | X         | 13 Mar 2035+30DY* | 3300DY    |
| RHC § 1.102 B. Perform 2200/2400 Hours Additional Component Maintenance                                                                                                                                                                                                                                          |               | 350b         |             |         |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         | 50FH  |          | X         | 4380:36+50FH*     | 1654:16FH |
| Tail Rotor Bellcrank - Replace with new                                                                                                                                                                                                                                                                          |               | 351          | OTL         | A120-3  |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH / 144MO |       |          | X         | 4380:36FH         | 1604:16FH |
| V-Belt Set - Replace with new                                                                                                                                                                                                                                                                                    |               | 354          | OTL         | A190-3  |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH / 144MO |       |          | X         | 4380:36FH         | 1604:16FH |
| Hoses - Replace with new: A785-6 bulkhead to MRGB                                                                                                                                                                                                                                                                |               | 361          | OTL         | A785-X  |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH / 144MO |       |          | X         | 4380:36FH         | 1604:16FH |
| Flex Plate Assy (intermediate) - Replace with new.                                                                                                                                                                                                                                                               |               | 364a         | OTL         | A947-2  |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| V-Belt - Alternator - Replace with new.                                                                                                                                                                                                                                                                          |               | 365          | OTL         | B173-3  | REV.H    |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH / 144MO |       |          | X         | 4380:36FH         | 1604:16FH |
| Hoses Assys - Replace with new: B283-3 fuel, various                                                                                                                                                                                                                                                             |               | 368          | OTL         | B283-X  |          |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH / 144MO |       |          | X         | 4380:36FH         | 1604:16FH |
| Main Rotor Hub (C154-1) & Bearing Assy - Perform inspection and repair per § 28-22, return to RHC for inspection and repair, or replace with new.                                                                                                                                                                |               | 371          | INSP        | C005-4  | 13103    | REV.X      | 2776:20 | 13.03.2023 | 2180:36 |      | 144MO          |       |          | X         | 13 Mar 2035       | 3270DY    |
| C016-7 Main Rotor Blades & C158-1 Spindle Assy - Submit to RHC-authorized component maintenance facility for 12-year service, or replace with new or overhaul exchange. 12-year maintenance includes blade replacement (as required), pitch horn screw replacement, boot and O-ring replacement, and inspection. |               | 372          | INSP        | C005-12 | REV.X    |            | 2776:20 | 07.11.2022 | 2180:18 |      | 144MO          |       |          | X         | 07 Nov 2034       | 3144DY    |
| C016-7 Main Rotor Blades & C158-1 Spindle Assy - Replace with new or overhaul exchange C005-12 main rotor blade & spindle assy, as required.                                                                                                                                                                     |               | 372a         | TBO         | C005-12 | REV.X    |            | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| Main Rotor Gearbox Assy - Submit to RHC Repair Station for 12-year service, or replace with new or overhaul exchange. 12-year maintenance includes pinion seal replacement, O-ring replacement, sealed bearing replacement, rubber mount replacement, and inspection.                                            |               | 373          | INSP        | C006-6  | 12120    | REV.AN     | 2776:20 | 13.03.2023 | 2180:36 |      | 144MO          |       |          | X         | 13 Mar 2035       | 3270DY    |
| Main Rotor Gearbox Assy - Replace with new or overhaul exchange C006-8 main rotor gearbox assy.                                                                                                                                                                                                                  |               | 373a         | TBO         | C006-6  | 12120    | REV.AN     | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |
| Fanshaft Assy - Inspect C181-3 bearing per § 2.502 step 3. Lubricate per § 1.140.                                                                                                                                                                                                                                |               | 374          | INSP        | C007-5  | 12032    | REV.AC     | 2776:20 | 13.03.2023 | 2180:36 |      | 144MO          |       |          | X         | 13 Mar 2035       | 3270DY    |
| Fanshaft Assy - Replace with new.                                                                                                                                                                                                                                                                                |               | 374a         | OTL         | C007-5  | 12032    | REV.AC     | 2776:20 | 13.03.2023 | 2180:36 | 0:00 | 2200FH         |       |          | X         | 4380:36FH         | 1604:16FH |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                                                                                                                                                     |               | Engine(s)    |                              | 1            |          |            |            |            |         |                |       |       |          |           |        |                         |                    |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--------------|------------------------------|--------------|----------|------------|------------|------------|---------|----------------|-------|-------|----------|-----------|--------|-------------------------|--------------------|
| TT:                                                                                                                                                                                                                                          | 2776:20       | TSO:         | 1576:08                      |              |          |            |            |            |         |                |       |       |          |           |        |                         |                    |
| Hobbs:                                                                                                                                                                                                                                       | 595:44        | Pn:          | O-540-F1B5                   |              |          |            |            |            |         |                |       |       |          |           |        |                         |                    |
| Type:                                                                                                                                                                                                                                        | R44 RAVEN I   | Sn:          | L-21252-40E                  |              |          |            |            |            |         |                |       |       |          |           |        |                         |                    |
| Sn:                                                                                                                                                                                                                                          | 2073          |              |                              |              |          |            |            |            |         |                |       |       |          |           |        |                         |                    |
| Description                                                                                                                                                                                                                                  | AD/SB/MOD No. | ATA / Action | Pn                           | Sn           | Curr. FH | Start date | Ac. TT     | LSV tem    | TT LSV  | TH             | Int.  | Ext.* | Open Ite | Appl. N/A | Due RT | Rem. RT                 |                    |
| Tail Rotor Assy - Disassemble. Remove bushings and teeter hinge bearings. Inspect hub; verify no fretting or corrosion. Fluorescent penetrant inspect hub. Replace blades as required. Replace teeter hinge bearings and blade attach bolts. |               | 376          | INSP                         | C008-9       | REV.W    |            | 2776:20    | 07.11.2022 | 2180:36 |                | 144MO |       |          |           | X      | 07 Nov 2034             | 3144DY             |
| Tail Rotor Assy - Replace with new C008-9 tail rotor assy.                                                                                                                                                                                   | 376a          | TBO          | C008-9                       | REV.W        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Swashplate Assy - Perform 12-year service per § 2.640, or replace with new or overhaul exchange.                                                                                                                                             | 380a          | INSP         | C017-6                       | 6608 REV.AG  |          | 2776:20    | 13.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 13 Mar 2035             | 3270DY             |
| Swashplate Assy - Replace with new or overhaul exchange C017-6 swashplate assy.                                                                                                                                                              | 380b          | TBO          | C017-6                       | 6608 REV.AG  |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Clutch Assy (C166-5 shaft) - Submit to RHC-authorized component maintenance facility, or replace with new or overhaul exchange. 12-year maintenance includes plug, seal and O-ring replacement. C184 bearing lubrication, and inspection.    | 381b          | INSP         | C018-4                       | REV.X        |          | 2776:20    | 13.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 13 Mar 2035             | 3270DY             |
| Clutch Assy (C166-5 shaft) - Replace with new or overhaul exchange C018-4 or -5 clutch assy.                                                                                                                                                 | 381c          | TBO          | C018-4                       | REV.X        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Tail Rotor Gearbox Assy - Perform 12-year service per § 2.610, or replace with new or overhaul exchange.                                                                                                                                     | 383           | INSP         | C021-1                       | 5359 REV.L   |          | 2776:20    | 13.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 13 Mar 2035             | 3270DY             |
| Tail Rotor Gearbox Assy - Replace with new or overhaul exchange.                                                                                                                                                                             | 383a          | TBO          | C021-1                       | 5359 REV.L   |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Tail Rotor Pitch Control - Replace with new.                                                                                                                                                                                                 | 384           | OTL          | C031-1                       | 14024 REV.M  |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4380:36FH / 13 Mar 2035 | 1604:16FH / 3270DY |
| Bearing Assy - TRDS damper - Replace with new.                                                                                                                                                                                               | 385           | TBO          | C041-11                      |              |          | 2776:20    | 13.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 13 Mar 2035             | 3270DY             |
| Clutch Actuator Assy - Replace with new or overhaul exchange.                                                                                                                                                                                | 388a          | TBO          | C051-1                       | 10686 REV.Z  |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Clutch Actuator Assy - Submit to RHC Repair Station for 12-year service, or replace with new or overhaul exchange.                                                                                                                           | 388a          | INSP         | C051-1                       | 10686 REV.Z  |          | 2776:20    | 22.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 22 Mar 2035             | 3279DY             |
| Push-Pull Tube (tailcone) - Replace with new.                                                                                                                                                                                                | 391b          | OTL          | C121-17                      |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Exhaust Muffler Assy - Replace C169-1 or -35 with new C169-35 assy // Replace C169-31 or -37 with new C169-37 assy.                                                                                                                          | 393a          | OTL          | C169-35                      | REV.R        |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Main Rotor Pitch Link Assy - Replace with new C258-5 link assy.                                                                                                                                                                              | 396           | OTL          | C258-5                       |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Swashplate Boot - Replace with new.                                                                                                                                                                                                          | 406           | OTL          | C480-1                       |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| 4-/5-point Harness Assy - Replace with new.                                                                                                                                                                                                  | 411           | OTL          | C627-X                       |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Connector Assy - Replace with new.                                                                                                                                                                                                           | 412           | OTL          | C628-X                       |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Oil Cooler - Flush & 400-psi pressure test or overhaul or replace with new.                                                                                                                                                                  | 413a          | INSP         | C649-2                       | 5652         |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4380:36FH / 13 Mar 2035 | 1604:16FH / 3270DY |
| Dual Tachometer - Submit to RHC repair station for 12-year service, or replace with new or overhaul exchange                                                                                                                                 | 416           | INSP         | C792-5                       | F21-10747    |          | 2776:20    | 13.03.2023 | 2180:36    |         |                | 144MO |       |          |           | X      | 13 Mar 2035             | 3270DY             |
| Dual Tachometer - Replace with new or overhaul exchange                                                                                                                                                                                      | 416a          | TBO          | C792-2                       | F21-10747    |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 2200FH         |       |       |          |           | X      | 4380:36FH               | 1604:16FH          |
| Yoke - Clutch Shaft Forward (1.43-inch dia. center hole between arms) - Replace with new C907-1 or -2 Rev. H or subsequent yoke.                                                                                                             | 417           | OTL          | C907-2 REV. A THRU G         | REV. UNKNOWN |          | 2776:20    | 21.03.2025 | 2629:49    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4829:49FH / 21 Mar 2037 | 2053:29FH / 4009DY |
| Yoke - Clutch Shaft Forward (1.43-inch dia. center hole between arms) - Replace with new, or comply with FAA AD 2025-11-07 (see current revision of R44 Service Letter SL-91).                                                               | 417b          | INSP/OTL     | C901-2 REV. H AND SUBSEQUENT | REV. UNKNOWN |          | 2776:20    | 21.03.2025 | 2629:49    | 0:00    | 2200FH / 144MO |       |       |          |           | X      | 4829:49FH               | 2053:29FH          |
| Flex Plate Assy (bonded) - Visually inspect with 10x magnification. Replace if corrosion is evident. Replace if any bonded washer evidences separation (8 places).                                                                           | 419           | INSP         | C947-3                       |              |          | 2776:20    | 13.03.2023 | 2180:36    | 0:00    | 144MO          |       |       |          |           | X      |                         |                    |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                                                                                                                                                                     |               | Engine(s)    |             | 1               |                                |            |            |         |        |    |                |              |          |           |                                      |                    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--------------|-------------|-----------------|--------------------------------|------------|------------|---------|--------|----|----------------|--------------|----------|-----------|--------------------------------------|--------------------|
| TT:                                                                                                                                                                                                          | 2776:20       | TSO:         | 1576:08     |                 |                                |            |            |         |        |    |                |              |          |           |                                      |                    |
| Hobbs:                                                                                                                                                                                                       | 595:44        | Pn:          | O-540-F1B5  |                 |                                |            |            |         |        |    |                |              |          |           |                                      |                    |
| Type:                                                                                                                                                                                                        | R44 RAVEN I   | Sn:          | L-21252-40E |                 |                                |            |            |         |        |    |                |              |          |           |                                      |                    |
| Sn:                                                                                                                                                                                                          | 2073          |              |             |                 |                                |            |            |         |        |    |                |              |          |           |                                      |                    |
| Description                                                                                                                                                                                                  | AD/SB/MOD No. | ATA / Action | Pn          | Sn              | Curr. FH                       | Start date | Ac. TT     | LSV tem | TT LSV | TH | Int.           | Ext.*        | Open Ite | Appl. N/A | Due RT                               | Rem. RT            |
| Engine Cooling Panels (consult IPC)                                                                                                                                                                          |               | 419          | OTL         | VARIOUS         |                                | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Flex Plate Assy (forward & aft) - Replace with new.                                                                                                                                                          |               | 419a         | OTL         | C947-1          |                                | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Fanwheel Assy - Perform 12-year service per § 2.620, or replace with new or overhaul exchange.                                                                                                               |               | 424          | INSP        | D174-2          |                                | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Fanwheel Assy - Replace with new or overhaul exchange.                                                                                                                                                       |               | 424a         | TBO         | D174-2          | REV. P                         | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Hydraulic Reservoir - Perform 12-year service per § 2.660, or replace with new or overhaul exchange.                                                                                                         |               | 430          | INSP        | D211-1          | 4270 REV.J                     | 2776:20    | 12.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 12 Mar 2035                          | 3269DY             |
| Hydraulic Reservoir - Replace with new or overhaul exchange.                                                                                                                                                 |               | 430a         | TBO         | D211-1          | 4270 REV.J                     | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Hydraulic Servo Actuators - Remove upper clevis, scissor, and D200-3 washer from servo, as applicable. Visually inspect threaded bore in pisont shaft with borescope. Replace servo if corrosion is evident. |               | 431          | INSP        | D212-1          | 1467A R.F / 9407 R.I / 11556 R | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Hydraulic Servo Actuators - Replace with new or overhaul exchange.                                                                                                                                           |               | 431a         | TBO         | D212-1          | 1467A R.F / 9407 R.I / 11556 R | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Tail Rotor Drive Shaft - Replace with new.                                                                                                                                                                   |               | 432a         | OTL         | D224-2          | 10932 REV.P                    | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Governor Controller Assy - Submit to RHC Repair Station for 12-year service, or replace with new or overhaul exchange.                                                                                       |               | 434          | INSP        | D278-1          | 3335 REV.E                     | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Governor Controller Assy - Replace with new or overhaul exchange.                                                                                                                                            |               | 434a         | TBO         | D278-1          | 3335 REV.E                     | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Hydraulic Pump - Replace with new or overhaul exchange.                                                                                                                                                      |               | 437          | TBO         | D500-1          | 7870 REV.I                     | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Bellcrank Assy (forward & aft, R44) - Visually inspect. Replace if corrosion is evident. Verify bearing rotates smoothly without noise.                                                                      |               | 445          | INSP        | D756-3 / D756-4 | REV. F                         | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Clutch Shaft                                                                                                                                                                                                 |               | 480          | TBO         | C166-4          | 3154 REV.R                     | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Clutch Shaft                                                                                                                                                                                                 |               | 481          | INSP        | C166-4          | 3154 REV.R                     | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Bearing Assy                                                                                                                                                                                                 |               | 482          | TBO         | C181-3          | 12032 REV.J                    | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Bearing Assy                                                                                                                                                                                                 |               | 483          | INSP        | C181-3          | 12032 REV.J                    | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Sprag Clutch                                                                                                                                                                                                 |               | 484          | TBO         | C188-3          | 14134 REV.H                    | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| Sprag Clutch                                                                                                                                                                                                 |               | 485          | INSP        | C188-3          | 14134 REV.H                    | 2776:20    | 13.03.2023 | 2180:36 |        |    | 144MO          |              |          | X         | 13 Mar 2035                          | 3270DY             |
| Main Rotor Drive Shaft                                                                                                                                                                                       |               | 487          | OH          | C251-2          | R9917 REV.T                    | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2200FH         |              |          | X         | 4380:36FH                            | 1604:16FH          |
| ENGINE OVERHAUL REQUIREMENTS LYC SI 1009 & MSB 240                                                                                                                                                           |               | 600          |             |                 |                                | 2776:20    |            |         | 0:00   |    |                |              |          | X         |                                      |                    |
| Replace Engine and all additional parts acc. LYC SI 1009                                                                                                                                                     | LYC_MSB-240AA | 601          | OH          | O-540-F1B5      | L-21252-40E                    | 2776:20    | 02.08.2012 | 2180:36 | 980:24 |    | 2000FH / 144MO | 200FH/2190DY |          | X         | 3200:12+200FH* / 02 Aug 2024+2190DY* | 623:52FH / 1585DY  |
| Magneto LH - Replace                                                                                                                                                                                         |               | 603          | OH          | 10-600616-3     | E09AA039                       | 2776:20    | 10.07.2024 | 2671:19 | 0:00   |    | 2000FH / 144MO | 200FH        |          | X         | 4671:19+200FH* / 10 Jul 2036         | 2094:59FH / 3755DY |
| Magneto RH - Replace                                                                                                                                                                                         |               | 604          | OH          | 10-600646-201   | D06AA087R                      | 2776:20    | 14.08.2023 | 2671:19 | 0:00   |    | 2000FH / 144MO | 200FH        |          | X         | 4671:19+200FH* / 14 Aug 2035         | 2094:59FH / 3424DY |
| Carburetor - Replace                                                                                                                                                                                         |               | 605          | OH          | 10-6035-11      | MS010102                       | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2000FH         | 200FH        |          | X         | 4180:36+200FH*                       | 1604:16FH          |
| Starter - Replace                                                                                                                                                                                            |               | 606          | OH          | BC315-100-2     | 0123120112                     | 2776:20    | 13.03.2023 | 2180:36 | 0:00   |    | 2000FH         | 200FH        |          | X         | 4180:36+200FH*                       | 1604:16FH          |
| Alternator - Replace                                                                                                                                                                                         |               | 608          | OH          | ALX-8521        | H-Y04059                       | 2776:20    | 29.04.2024 | 2405:30 | 0:00   |    | 2000FH         | 200FH        |          | X         | 4405:30+200FH*                       | 1829:10FH          |
| ADDITIONAL REQUIREMENTS                                                                                                                                                                                      |               | 650          |             |                 |                                | 2776:20    |            |         | 0:00   |    |                |              |          | X         |                                      |                    |

OE-XXY - Recurring Maintenance (All)

| Aircraft                                                               |               | Engine(s)    |             |         |           |          |            |            |         |        |    |       |       |          |  |           |                   |         |
|------------------------------------------------------------------------|---------------|--------------|-------------|---------|-----------|----------|------------|------------|---------|--------|----|-------|-------|----------|--|-----------|-------------------|---------|
| TT:                                                                    | 2776:20       | TSO:         | 1576:08     |         |           |          |            |            |         |        |    |       |       |          |  |           |                   |         |
| Hobbs:                                                                 | 595:44        | Pn:          | O-540-F1B5  |         |           |          |            |            |         |        |    |       |       |          |  |           |                   |         |
| Type:                                                                  | R44 RAVEN I   | Sn:          | L-21252-40E |         |           |          |            |            |         |        |    |       |       |          |  |           |                   |         |
| Sn:                                                                    | 2073          |              |             |         |           |          |            |            |         |        |    |       |       |          |  |           |                   |         |
| Description                                                            | AD/SB/MOD No. | ATA / Action | Pn          | Sn      |           | Curr. FH | Start date | Ac. TT     | LSV tem | TT LSV | TH | Int.  | Ext.* | Open Ite |  | Appl. N/A | Due RT            | Rem. RT |
| ELT Battery - Replace                                                  |               | 651          | LL          | All     |           | 2776:20  | 30.09.2023 |            |         |        |    | 72MO  |       |          |  | X         | 30 Sep 2029       | 1280DY  |
| Halon Fire Extinguisher - Replace                                      |               | 653          | LL          | RT-A400 | D58314781 |          | 2776:20    | 31.12.2022 |         |        |    | 144MO |       |          |  | X         | 31 Dec 2034       | 3198DY  |
| Check that current POH Revision is installed                           |               | 656          | INSP        |         |           | 2776:20  | 09.04.2025 |            | 2576:50 | 0:00   |    | 12MO  | 15DY  | X        |  | X         | 05 Apr 2026+15DY* | 21DY    |
| Check that current Pilot Checklist is installed                        |               | 657          | INSP        |         |           | 2776:20  | 09.04.2025 |            | 2576:50 | 0:00   |    | 12MO  | 15DY  | X        |  | X         | 05 Apr 2026+15DY* | 21DY    |
| Check all placards acc. POH Chapter 2 and IPC 11-1. Renew if necessary |               | 658          | CHK         |         |           | 2776:20  | 09.04.2025 |            | 2576:50 |        |    | 12MO  |       | X        |  | X         | 09 Apr 2026       | 10DY    |