

D-HEAD - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 8118:06	TSO: 1590:24	
Hobbs: 3815:42	Pn: O-320-B2C	
Type: R22 BETA	Sn: L-17039-39A	
Sn: 0988		

Description	Task No.	Action	Pn	Sn	TH	Int.	Ext.*	Ac. TT LSV	Start date	Rem.	Due
European Requirements	000										
Full Airworthiness Review	001	INSP				36MO			17.09.2020	21MO	17.09.2023
ARC Extension	002	INSP				12MO		8076:06	17.09.2021	9MO	17.09.2022
EASA SIB 2011-15R2 - Mode S Transponder Check	003	INSP				24MO	30DY	8098:18	05.10.2021	22MO*	19.10.2023
EASA SIB 2019-09R1 - ELT Annual Testing	004	INSP				12MO	15DY	8098:18	05.10.2021	9MO*	25.09.2022
Check each static pressure system, each altimeter instrument, and each automatic pressure altitude reporting system acc. CFR § 91.411	005	INSP				24MO	30DY	8098:18	05.10.2021	22MO*	19.10.2023
First Aid Kit	006	INSP				12MO	15DY	7990:00	18.02.2021	3MO*	05.03.2022
Compass Compensation acc. FAR 23.1547 & 23.1327	006	INSP				24MO	30DY	7936:48	29.10.2020	11MO*	28.11.2022
Fire Extinguisher	007	INSP				12MO	15DY	7990:00	18.02.2021	3MO*	05.03.2022
Weighing (CAT)	009	INSP				48MO	30DY	7650:18	28.06.2019	19MO*	28.07.2023
Kannad SB S1800000-25, current revision (recommended) - Check of hook and loop fasteners for mounting mechanism	060	INSP				12MO	15DY	8098:18	07.10.2021	9MO*	25.09.2022
Kannad AF - Periodically Inspection iaw. DOC09078A Ref. 0146257A	065	INSP				12MO			01.04.2021	4MO	01.04.2022
Kannad AF - 6 Years Inspection iaw. DOC09078A Ref. 0146257A	070	INSP				72MO			01.04.2016	4MO	01.04.2022
Scheduled Maintenance Airframe	100										
RHC § 2.700 - 2200-hour maintenance (Overhaul)	101	INSP				2200FH		6591:00	24.08.2015	672:54FH	8791FH
RHC § 2.600 - 12-year maintenance	102	INSP				144MO		6591:00	24.08.2015	68MO	24.08.2027
RHC § 2.400 - 100-hour/annual maintenance	103	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	81:54FH*/10MO*	8200FH/22.10.2022
RHC § 2.400 - Ground & Flight Check for 100hour/annual maintenance	104	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	81:54FH*/10MO*	8200FH/22.10.2022
RHC § 22-42 - Perform clutch assembly lubricant inspection & servicing	105	INSP				500FH	25FH	8098:18	07.10.2021	505:12FH*	8623:18FH
RHC § 22-13 - Drain and flush MR Gearbox	108	INSP				500FH	25FH	8098:18	07.10.2021	505:12FH*	8623:18FH
RHC § 22-23 - Drain and flush TR Gearbox	109	INSP				500FH	25FH	8098:18	07.10.2021	505:12FH*	8623:18FH
RHC §§ 22-11 & 22-21 - Clean gearbox chip detectors	110	INSP				500FH/12MO	25FH/15DY	8040:00	30.06.2021	446:54FH*/5MO*	8565FH/23.05.2022
RHC § 22-42 - Lubricate A181-4 Rev. N bearings	112	INSP				800FH/48MO	40FH/30DY	7364:42	28.05.2018	86:36FH*/6MO*	8204:42FH/27.06.2022
RHC § 22-41 (SB-89) - Lubricate A184 bearings	113	INSP				300FH/12MO	15FH/15DY	8040:00	30.06.2021	236:54FH*/5MO*	8355FH/23.05.2022
RHC SL-58 / EASA SIB 2012-06/2014-12 - Standard Hardware, AN, MS, NAS Fasteners	115	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	81:54FH*/10MO*	8200FH/22.10.2022
RHC SL-62 - Air Filter Inspection	116	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	81:54FH*/10MO*	8200FH/22.10.2022
RHC SL-62 - Air Filter Replacement	117	REPL				600FH/60MO	30FH/30DY	7879:18	31.07.2020	391:12FH*/44MO*	8509:18FH/30.08.2025
RHC § 26.60 (RHC SL-83) - MRB Tip Maintenance	118	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	81:54FH*/10MO*	8200FH/22.10.2022
RHC SB-60A / FAA AD 88-26-01 R2 / LTA HB 90-329 / LTA 1988-282 R3 - A158-1 main rotor spindle and A106 journals	120	INSP				500FH		7936:48	29.10.2020	318:42FH	8436:48FH
Critical Tasks: The Maintenance Organisation has to follow the manufacturer instructions and regulations acc. Part-M/ML and Part-145.	121	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
ELT Security	131	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	90:12FH*/10MO*	8208:18FH/22.10.2022
Tail Rotor Blade Condition and Care	132	INSP				100FH/12MO	10FH/15DY	8098:18	07.10.2021	90:12FH*/10MO*	8208:18FH/22.10.2022
Scheduled Engine Engine	200										

D-HEAD - Recurring Maintenance (All)

Aircraft		Engine(s)	1
TT:	8118:06	TSO:	1590:24
Hobbs:	3815:42	Pn:	O-320-B2C
Type:	R22 BETA	Sn:	L-17039-39A
Sn:	0988		

Description	Task No.	Action	Pn	Sn	TH	Int.	Ext.*	Ac. TT LSV	Start date	Rem.	Due
LYC § 04.4 - 50-Hour Inspection	204	INSP				50FH	10FH	8098:18	07.10.2021	28:42FH*	8146:48FH
LYC § 04.5 - 100-Hour Inspection	205	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
LYC § 04.6 - 400-Hour Inspection (Shorter Intervall)	206	INSP				300FH	15FH	8040:00	30.06.2021	236:54FH*	8355FH
LYC SI-1129D Method of checking DC Alternator Belt Tension	207	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
LYC SI-1191A - Cylinder Compression	208	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
LYC SI-1080C - Maintenance Items for special attention	209	INSP				50FH	10FH	8098:18	07.10.2021	28:42FH*	8146:48FH
LYC SB-301C - Maintenance Procedure and Service Limitation for Valves (First 100hrs acc. RHC MM Rev. NOV 2020)	210	INSP				100FH	300FH	8040:00	30.06.2021	236:54FH*	8355FH
LYC SB-388C / EASA AD 2005-0023R3 - Procedure to Determine Exhaust Valve and Guide Condition	212	INSP				300FH	30FH	8040:00	30.06.2021	251:54FH*	8370FH
LYC SB-480F - Oil & Oil Filter Change	213	INSP				50FH/4MO	10FH/15DY	8098:18	07.10.2021	28:42FH*/2MO*	8146:48FH/22.02.2022
LYC SB-183A - Magneto to Engine Timing	214	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
Scheduled Magneto Maintenance LH	250	INSP									
CMI SB-643C - LH Magneto 100 Hours	251	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
CMI SB-643C - LH Magneto 500 Hours	252	INSP	BL-600614-1	E14KA0283		500FH/48MO	25FH/30DY	7942:12	19.10.2020	349:06FH*/35MO*	8467:12FH/18.11.2024
CMI SB-670 - LH - Replacement and maintenance of Magneto Distributer Block	255	INSP	BL-600614-1	E14KA0283		500FH/48MO	25FH/30DY	7942:12	19.10.2020	349:06FH*/35MO*	8467:12FH/18.11.2024
Scheduled Magneto Maintenance RH	260										
CMI SB-643C - RH Magneto 100 Hours	261	INSP				100FH	10FH	8098:18	07.10.2021	81:54FH*	8200FH
CMI SB-643C - RH Magneto 500 Hours	262	INSP	10-600644-20 1	E04CA268		500FH/48MO	25FH/30DY	7936:46	14.05.2020	343:40FH*/30MO*	8461:46FH/13.06.2024
CMI SB-663 - RH - Two-Wire Magneto Tach Breaker Contact (Points) Assy. P/N 10-400507	264	INSP	10-600644-20 1	E04CA268		500FH/48MO	25FH/30DY	7936:46	14.05.2020	343:40FH*/30MO*	8461:46FH/13.06.2024
CMI SB-670 - RH - Replacement and maintenance of Magneto Distributer Block	265	INSP	10-600644-20 1	E04CA268		500FH/48MO	25FH/30DY	7936:46	14.05.2020	343:40FH*/30MO*	8461:46FH/13.06.2024
Airframe Fatigue Life Limited Parts/Overhaul	300										
Coning Hinge Bolt (Flight (collective up) Time)	344	LL	NAS630-80			1964FH		6591:00		436:54FH	8555FH
Pitch Horn Screws (Flight (collective up) Time)	346	LL	NAS1351-4-2 0			1964FH		6591:00		436:54FH	8555FH
Main Rotor Spindle (Flight (collective up) Time)	349	LL	A158-1	20302 REV.AA		2156FH		6591:00		628:54FH	8747FH
Main Rotor Spindle (Flight (collective up) Time)	350	LL	A158-1	20303 REV.AR		2156FH		6591:00		628:54FH	8747FH
Main Rotor Blade (Flight (collective up) Time)	351	LL	A016-6	1228 REV.AR		2200FH/144MO		6591:00	17.08.2012	672:54FH/32MO	8791FH/17.08.2024
Tail Rotor Blade (Flight (collective up) Time)	355	LL	A029-2	5516 REV.AC		2200FH/144MO		6591:00	07.09.2012	672:54FH/33MO	8791FH/07.09.2024
Tail Rotor Blade (Flight (collective up) Time)	356	LL	A029-2	5517 REV.AC		2200FH/144MO		6591:00	07.09.2012	672:54FH/33MO	8791FH/07.09.2024
Pinion, Main Gearbox (Flight (collective up) Time)	357	LL	A146-1	11386 REV.Q		2200FH		6591:00	24.08.2015	672:54FH	8791FH
Sprag Clutch Assy (Flight (collective up) Time)	360	LL	A188-2	10063 REV.AD		2200FH		6591:00	24.08.2015	672:54FH	8791FH
Bearing, Main Rotor Shaft (Flight (collective up) Time)	361	LL	A647-1			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Bearing, Tail Rotor Pitch Control (Flight (collective up) Time)	362	LL	A647-6			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Bearing, Damper Assy (Flight (collective up) Time)	363	LL	A647-8			2200FH/144MO		6591:00	06.09.2012	672:54FH/33MO	8791FH/06.09.2024

D-HEAD - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 8118:06	TSO: 1590:24	
Hobbs: 3815:42	Pn: O-320-B2C	
Type: R22 BETA	Sn: L-17039-39A	
Sn: 0988		

Description	Task No.	Action	Pn	Sn	TH	Int.	Ext.*	Ac. TT LSV	Start date	Rem.	Due
Gear Set, Tail Gearbox (Flight (collective up) Time)	364	LL	B545-1			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Tail Rotor Balde-to-Hub Attach Bolt (Flight (collective up) Time)	367	LL	NAS1304			2200FH		6591:00		672:54FH	8791FH
Main Rotor Hub (Flight (collective up) Time)	369	LL	A154-1	6394 REV.M		3928FH		6591:00	24.08.2015	672:54FH	8791FH
Upper Frame, Rev. S & Subsequent (Flight (collective up) Time)	370	LL	A020-2	6169 REV.AI		4400FH		6591:00	24.08.2015	684:06FH	8802:12FH
Tailcone Assy (Flight (collective up) Time)	374	LL	A023-20	5539 REV.AM		4400FH		6591:00	25.08.2015	684:06FH	8802:12FH
Lower R.H. Frame (Flight (collective up) Time)	377	LL	A046-2	5208 REV.N		4400FH		6591:00	24.08.2015	672:54FH	8791FH
Tail Rotor Hub (Flight (collective up) Time)	380	LL	A062-2	5323 REV.AC		4400FH		6591:00	24.08.2015	2872:54FH	10991FH
A154-1 Main Rotor Hub & Bearing Assy - Perform inspection and repair per MM § 2.610, return to RHC for inspection and repair, or replace with new.	383	INSP	A005-4			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
A016-6 Main Rotor Blade & A158-1 Spindle Assy - Submit to RHC-authorized component maintenance facility for 12-year maintenance, or replace with new or overhaul.	387	INSP	A005-7			144MO		6591:00	17.08.2012	32MO	17.08.2024
Main Rotor Gearbox Assy - Submit to RHC-authorized component maintenance facility for 12-year maintenance, or replace with new or overhaul.	392	INSP	A006-6	2943 REV.AQ		144MO		6591:00	24.08.2012	32MO	24.08.2024
Fanshaft Assy - Replace with new A007-5 fanshaft assy	394	LL	A007-5			2200FH/144MO		6591:00	31.08.2012	672:54FH/32MO	8791FH/31.08.2024
Tail Rotor Assy - Replace with new A008-4 tail rotor assy	396	LL	A008-4			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Swashplate Assy - Submit to RHC-authorized component maintenance facility for 12-year maintenance, or replace with new or overhaul.	398	INSP	A017-2	4438 REV.AH		144MO		6591:00	24.08.2012	32MO	24.08.2024
Clutch Assy (anodized) - Submit to RHC-authorized component maintenance facility for 12-year maintenance, or replace with new or overhaul.	399	INSP	A018-1			144MO		6591:00	06.09.2012	33MO	06.09.2024
Tail Rotor Pitch Control - Replace with new	403	LL	A031-1	5010 REV.L		2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Tail Rotor Drive Shaft Damper Bearing Assy - Replace with new A041-11 damper bearing assy or replace with new B224-1 or -3 drive shaft.	404	LL	A041-11			2200FH/144MO		6591:00	06.09.2012	672:54FH/33MO	8791FH/06.09.2024
Tail Rotor Drive Shaft Damper Bearing Assy - Replace with new A041-12 damper bearing assy or replace with new B224-1 or -3 drive shaft.	405	LL	A041-12			2200FH/144MO		6591:00	06.09.2012	672:54FH/33MO	8791FH/06.09.2024
Clutch Actuator Assy (A051-1 includes gearmotor assy) - Replace with new or overhaul.	407	OH	A051-1	6080 REV.AP		2200FH/144MO		6591:00	06.09.2012	672:54FH/33MO	8791FH/06.09.2024
Tail Rotor Bellcrank - Replace with new	409	LL	A120-1			2200FH/144MO		6591:00	24.08.2015	672:54FH/68MO	8791FH/24.08.2027
Muffler with Risers (O-320 engine) - Visually inspect muffler interior	414	INSP	A169-35			144MO		6591:00	28.07.2012	31MO	28.07.2024
V-Belt Set - Replace with new A190-2 v-belt set	417	LL	A190-1			2200FH/144MO		7706:12	20.09.2012	1788:06FH/33MO	9906:12FH/20.09.2024
Flex Plate - Replace with new A947-2 flex plate assy	419	LL	A193-2			2200FH/144MO		6591:00	20.09.2012	672:54FH/33MO	8791FH/20.09.2024
Flex Plate - Replace with new A947-3 flex plate assy	420	LL	A193-3			2200FH/144MO		6591:00	20.09.2012	672:54FH/33MO	8791FH/20.09.2024
Main Rotor Pitch Link Assy - Replace with new A258-1 or A258-2 link assy	428	LL	A258-1			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Swashplate Boot - Replace with new	430	LL	A480-1			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Oil Cooler - Replace with new or overhaul exchange C649-1 oil cooler.	434	LL	C649-1/10614 T	2483		2200FH/144MO		6591:00	24.08.2015	672:54FH/68MO	8791FH/24.08.2027
Hose - Air (intake) - Replace with new	435	LL	A785-1			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Hose - Air (hot air inlet) - Replace with new	436	LL	A785-2			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Hose - Air (engine cooling) - Replace with new	437	LL	A785-6			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Hose - Air (alternator cooling) - Replace with new	438	LL	A785-7			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Hose - Air (hot air inlet) - Replace with new	439	LL	A785-26			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Hose - Replace with new	440	LL	A785-32			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024

D-HEAD - Recurring Maintenance (All)

Aircraft		Engine(s)	1
TT: 8118:06		TSO: 1590:24	
Hobbs: 3815:42		Pn: O-320-B2C	
Type: R22 BETA		Sn: L-17039-39A	
Sn: 0988			

Description	Task No.	Action	Pn	Sn	TH	Int.	Ext.*	Ac. TT LSV	Start date	Rem.	Due
Dual Tachometer - Replace with new or overhaul exchange A792-4 dual tachometer	442	OH	A792-4	3399		2200FH/144MO		6591:00	06.09.2012	672:54FH/33MO	8791FH/06.09.2024
Tail Rotor Gearbox Assy - Perform 12-year maintenance per MM § 2.620, or replace with new or overhaul exchange.	443	INSP	B021-1	2198 REV.H		144MO		6591:00	06.09.2012	33MO	06.09.2024
V-belt- Alternator - Replace with new	444	LL	B179-1			2200FH/144MO		6591:00	24.08.2012	672:54FH/32MO	8791FH/24.08.2024
Fanwheel (Rev. J or subsequent) - Perform 12-year maintenance per MM § 2.620, or replace with new or overhaul exchange.	445	INSP	B174-1			144MO		6591:00	06.09.2012	33MO	06.09.2024
Hose Assy (fuel system) Rev. A thru P - Replace with new	446	LL	B283-1			2200FH/144MO		6591:00	24.08.2015	672:54FH/68MO	8791FH/24.08.2027
Hose Assy (fuel system) Rev. A thru P - Replace with new	447	LL	B283-2			2200FH/144MO		6591:00	24.08.2015	672:54FH/68MO	8791FH/24.08.2027
Hose Assy (fuel system) Rev. A thru P - Replace with new	448	LL	B283-6			2200FH/144MO		6591:00	24.08.2015	672:54FH/68MO	8791FH/24.08.2027
Governor Controller - Replace with new or overhaul exchange.	449	OH	B286-2	3423		2200FH/144MO		6591:00	24.07.2012	672:54FH/31MO	8791FH/24.07.2024
Bellcrank Assy - Throttle - Replace with new.	450	LL	D752-2			2200FH/144MO		6592:06	07.09.2012	674FH/33MO	8792:06FH/07.09.2024
A016-6 Main Rotor Blade & A158-1 Spindle Assy - Replace with new or overhaul exchange A005-7 or A005-14 main rotor blade & spindle assy	454	OH	A005-7			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Main Rotor Gearbox Assy - Replace with new or overhaul exchange A006-6 main rotor gearbox assy	459	OH	A006-6	2943 REV.AQ		2200FH		6591:00	24.08.2015	672:54FH	8791FH
Swashplate Assy - Submit to RHC-authorized component maintenance facility for overhaul, or replace with new or overhaul exchange.	460	OH	A017-2	4438 REV.AH		2200FH		6591:00	24.08.2015	672:54FH	8791FH
Clutch Assy (anodized) - Replace with new or overhaul exchange	461	OH	A018-1			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Muffler with Risers (O-320 engine) - Replace with new A169-35 muffler	464	LL	A169-35			2200FH		6591:00	24.08.2024	672:54FH	8791FH
Nut - Double Lock - Replace with new	467	LL	A189-10			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Cap - Collective Spring - Replace with new	468	LL	A426-6			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Gasket - Carberot-to-Air Box - Replace with new	469	LL	A615-1			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Connector Assy - Harness - Replace with new	470	LL	A628-4			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Connector Assy - Harness - Replace with new	470	LL	A628-4			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Buckle Assy	470	LL	A628-5			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Buckle Assy	470	LL	A628-5			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Support (O-320 engine) - Replace with new	471	LL	A636-2			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Oil Line Assy - Replace with new A723-5 oil line assy	472	LL	A723-1			2200FH		6592:06	22.10.2015	674FH	8792:06FH
Oil Line Assy - Replace with new A723-6 oil line assy	473	LL	A723-2			2200FH		6592:06	15.10.2015	674FH	8792:06FH
Cable Assy - Replace with new	474	LL	A780-33			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Flex Plate Assy - Forward - Replace with new	475	LL	A947-1			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Flex Plate Assy - Intermediate - Replace with new	476	LL	A947-2			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Flex Plate Assy - Aft - Replace with new	477	LL	A947-3			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Tail Rotor Gearbox Assy - Replace with new or overhaul exchange	478	OH	B021-1	2198 REV.H		2200FH		6592:06	07.09.2012	674FH	8792:06FH
Fanwheel (Rev. J or subsequent) - Replace with new or overhaul exchange	479	OH	B174-1			2200FH		6591:00	24.08.2015	672:54FH	8791FH
Tail Rotor Drive Shaft - Replace with new	480	LL	B224-1	7194 REV.G		2200FH		6591:00	24.08.2015	672:54FH	8791FH
Pin - Spring (fanshaft nut) - Replace with new	482	LL	B350-2			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Buckle Assy - Replace with new	484	LL	F628-8			2200FH		6592:06	28.07.2012	674FH	8792:06FH

D-HEAD - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 8118:06	TSO: 1590:24	
Hobbs: 3815:42	Pn: O-320-B2C	
Type: R22 BETA	Sn: L-17039-39A	
Sn: 0988		

Description	Task No.	Action	Pn	Sn	TH	Int.	Ext.*	Ac. TT LSV	Start date	Rem.	Due
R22 Bladder Fuel Tank Installation Kit - Required for helicopter S/N 0002 thru 4620 per SB-109, if not previously accomplished	485	INST	KI-217-1			2200FH		6591:00		672:54FH	8791FH
Nut - Fanshaft - Replace with new	488	LL	AN320-18			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Pin - Spring - Replace with new	489	LL	MS16562-15			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Washer - Replace with new	490	LL	MS20002-18			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Cotter Pin - Replace with new	491	LL	MS24665-355			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Washer - Replace with new	492	LL	NAS1149F18 32P			2200FH		6592:06	28.07.2018	674FH	8792:06FH
Bolt - Replace with new	493	LL	NAS6604-80			2200FH		6592:06	28.07.2012	674FH	8792:06FH
Additional Requirements	550										
ELT Battery	551	LL	S1840501-01	2619925-013 6		72MO			01.04.2016	4MO	01.04.2022
Fire Extinguisher	553	LL	RT-A400	X-718491		144MO			05.08.2012	32MO	05.08.2024
First Aid Kit	555	REPL				72MO		8098:18	07.10.2021	70MO	07.10.2027
Engine Overhaul	600										
Engine	602	OH	O-320-B2C	L-17039-39A		2200FH/144MO		6591:00	14.10.2013	609:36FH/46MO	8727:42FH/14.10.2025
Magneto LH	603	OH	BL-600614-1	E14KA0283		2200FH/144MO		7942:12	19.10.2020	2024:06FH/130MO	10142:12FH/19.10.2032
Magneto RH	604	OH	10-600644-20 1	E04CA268		2200FH/144MO		7936:46	14.05.2020	2018:40FH/125MO	10136:46FH/14.05.2032
Carburetor	605	OH	10-5217	75877805		2200FH/144MO		6591:00	14.10.2013	609:36FH/46MO	8727:42FH/14.10.2025
Starter	606	OH	BC315-100-2	0103000112		2200FH		6591:00	27.03.2019	672:54FH	8791FH
Alternator	607	OH	ALY-8520-R	H-N080530		2200FH		6591:00	24.08.2015	609:36FH	8727:42FH