



R-44 MAINTENANCE PROGRAM

AIRFRAME INSPECTION PROGRAM

LN-OCJ

AC Serial number 0103 | AC Total time 3,983.60 HRS at date 05.02.2019

ATA	REF	REQUIREMENT DESCRIPTION	TASK TYPE	TASK INTERVAL	LAST INSPECTION		DUE AT		REMAINING		PRI
					TIME	DATE	TIME	DATE	TIME	DYS	
04	04/CAME /	Perform Annual Airworthiness Review.	CHK	365 DYS	3908.00 HRS	13.06.2018		26.06.2019	133.00	133	man
05	05/R44/1 506	Special Inspection	CHK				0.00		0.00		man
05	05/R44/1 502	50 Hrs Inspection Engine.	CHK	50 HRS	3975.50 HRS	30.11.2018	4,025.50	06.03.2019	42.00	21	man
05	05/R44/1 503	100 Hrs / 12 Month Inspection	CHK	100 HRS	3940.00 HRS	31.07.2018	4,030.90	09.03.2019	47.00	24	man
05	05/R44/1 503	100 Hrs / 12 Month Inspection	CHK	365 DYS	3940.00 HRS	31.07.2018		31.07.2019	168.00	168	man
05	05/R44/1 505	2200 Hrs Inspection: OH	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
05	05/R44/1 504	12 Years Inspection	CHK	4380 DYS	2002.00 HRS	29.05.2008		26.05.2020	468.00	468	man
08	08/CAT/P OL/MAB/ 100	Aircraft Weighing	CHK	1460 DYS				08.03.2020	389.00	389	man
21	21/10/10	Hoses, air ducts (various dash numbers): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
21	21/10/10	Hoses, air ducts (various dash numbers): SLL	CHK	4380 DYS	2002.00 HRS	29.05.2008		26.05.2020	468.00	468	man
24	24/10/00	Battery Cables (various dash numbers): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
25	25/CAT/I DE/A/220	First Aid Kit	CHK	365 DYS	3865.10 HRS	06.03.2018		06.03.2019	21.00	21	man
25	25/10/10	4-Point Harness & Buckle Assemblies: SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
34	34/10/20	Pitot Static System : CHK	CHK	730 DYS	3865.10 HRS	06.03.2018		05.03.2020	386.00	386	man
62	R44/SL- 31	Main Rotor Blade Inspection. Tap test outboard tips of C934 doublers (top and bottom of blade)	CHK	100 HRS	3940.00 HRS	31.07.2018	4,030.20	09.03.2019	47.00	24	rec
67	67/00/00	Service collective spring (manual controls)	CHK	500 HRS	3754.60 HRS	17.04.2017	4,254.60	29.06.2019	271.00	136	man
71	71/10/10	Engine cooling panels (consult IPC): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
71	72/10/10	Alternator Belt: SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
71	72/10/10	Alternator Belt: SLL	CHK	4380 DYS	2002.00 HRS	29.05.2008		26.05.2020	468.00	468	man
78	1/1	DDL: Exhaust muffler shroud cracked, ref Skytec WP: 17-232.					4,400.00	09.09.2019	416.00	208	
78	78/10/10	Muffler with risers (various dash numbers): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
79	79/10/10	Oil lines (various dash numbers): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
79	79/10/11	Hose Assemblies (various dash numbers): SLL	CHK	2200 HRS	2002.00 HRS	29.05.2008	4,202.00	02.06.2019	218.00	109	man
79	79/10/11	Hose Assemblies (various dash numbers): SLL	CHK	4380 DYS	2002.00 HRS	29.05.2008		26.05.2020	468.00	468	man

Due at date is calculated based on average values defined for this aircraft and remaining dys is calculated from this.