

D-HUBI - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3751:06	TSO: 1715:36	
Hobbs: 3751:06	Pn: O-540-F1B5	
Type: R44	Sn: L-26650-40A	
Sn: 0725		

Description	AD/SB/MOD IATA / 1	Action Pn	Sn	Curr. FH	Start date Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
European Requirements	000				3751:06								
Full Airworthiness Review	001	INSP			3751:06	03.07.2021	2674:42	36MO		8MO	03.07.2024	03 Jul 2024	218DY
ARC Extension	002	INSP			3751:06	03.07.2023	3537:06	12MO		8MO	03.07.2024	03 Jul 2024	218DY
EASA SIB 2011-15R2 - Mode S Transponder Check	003	INSP			3751:06	24.05.2023	3474:18	24MO	30DY	19MO*	23.06.2025*	24 May 2025+30DY*	573DY
Check each static pressure system, each altimeter instrument, and each automatic pressure altitude reporting system acc. CFR § 91.411	005	INSP			3751:06	24.05.2023	3474:18	24MO	30DY	19MO*	23.06.2025*	24 May 2025+30DY*	573DY
Compass Compensation acc. FAR 23.1547 & 23.1327	006	INSP			3751:06	05.05.2022	3041:18	24MO	30DY	7MO*	04.06.2024*	05 May 2024+30DY*	189DY
First Aid Kit	008	INSP			3751:06	01.04.2023	3424:48	12MO	15DY	5MO*	16.04.2024*	01 Apr 2024+15DY*	140DY
Perform Weight & Balance (AMC1 CAT.POL.MAB.100(b)) and replace POH W&B Report & Equipmentlist	009	INSP			3751:06	12.01.2021	2615:00	48MO	30DY	15MO*	11.02.2025*	12 Jan 2025+30DY*	441DY
Scheduled Maintenance Airframe	100	INSP			3751:06								
RHC § 2.600 - 2200-hour inspection (R44 / R44 II)	101	INSP			3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
RHC § 2.600 - 12-Year inspection	102	INSP			3751:06	28.12.2016	2035:30	144MO		61MO	28.12.2028	28 Dec 2028	1857DY
RHC § 2.200 - Ground & Flight Check for 100hour/Annual Inspection	103a	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC § 2.300 - Airframe Preparation for 100-Hour/Annual Inspection	103b	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC § 2.400 - 100-hour/Annual Airframe Inspection	104	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC § 7.210 - Perform clutch assembly lubricant inspection & servicing	105	INSP			3751:06	24.05.2023	3474:18	500FH	25FH	248:12FH*	3999:18FH*	3974:18+25FH*	248:12FH
RHC § 1.120 - Drain and flush MGB	108	INSP			3751:06	24.05.2023	3474:18	4FH 500FH	25FH	248:12FH*	3999:18FH*	3974:18+25FH*	248:12FH
RHC § 1.130 - Drain and flush TGB	109	INSP			3751:06	24.05.2023	3474:18	4FH 500FH	25FH	248:12FH*	3999:18FH*	3974:18+25FH*	248:12FH
RHC § 1.115 - Clean gearbox chip detectors	110	INSP			3751:06	01.04.2023	3424:48	4FH 500FH / 12MO	25FH/15 DY	198:42FH*/5M O*	3949:48FH*/16.04.2024*	3924:48+25FH* / 01 Apr 2024+15DY*	198:42FH / 140DY
RHC § 1.140 - Lubricate C181-3 bearings	111	INSP			3751:06	24.05.2023	3474:18	300FH / 36MO	15FH/30 DY	38:12FH*/31M O*	3789:18FH*/23.06.2026*	3774:18+15FH* / 24 May 2026+30DY*	38:12FH / 938DY
RHC § 1.140 - Perform Ground Run after bearing lubrication	112	INSP			3751:06	24.05.2023	3474:18	300FH / 36MO	15FH/30 DY	38:12FH*/31M O*	3789:18FH*/23.06.2026*	3774:18+15FH* / 24 May 2026+30DY*	38:12FH / 938DY
RHC § 1.170 - Replace hydraulic filter	113	INSP			3751:06	24.05.2023	3474:18	300FH	15FH	38:12FH*	3789:18FH*	3774:18+15FH*	38:12FH
RHC SL-38 - Cracked MS2142L-Nuts Inspection	122	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC SL-43 - C343-1 Rev. L and prior Push-Pull Tube Inspection	123	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC SL-46 - Clean Air Filter P/N B771-1/B771-2	124	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC SL-46 - Air Filter Replacement P/N B771-1/B771-2	125	INSP			3751:06	21.09.2023	3690:42	600FH / 60MO	30FH/30 DY	569:36FH*/59 MO*	4320:42FH*/21.10.2028*	4290:42+30FH* / 21 Sep 2028+30DY*	569:36FH / 1789DY
RHC SL-50 - D210 Corrosion-Resistant (CRES) Nuts	126	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC SL-64A - Fire Extinguisher Handling & Maintenance P/N B381-(RT-A400)	127	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
RHC § 28-60 (RHC SL-70) - Main Rotor Blade Tip Maintenance	128	INSP			3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M O*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY

D-HUBI - Recurring Maintenance (All)

Aircraft		Engine(s)		1								
TT:	3751:06	TSO:	1715:36									
Hobbs:	3751:06	Pn:	O-540-F1B5									
Type:	R44	Sn:	L-26650-40A									
Sn:	0725											
Description	AD/SB/MOD IATA / 1	Action Pn	Sn	Curr. FH	Start date Ac. TT LSV TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT	
Airwolf Filter Inspection / Cleaning acc. AFC-W324_Rev_X	132	INSP		3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M 24*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
ELT Security (FAA SAIB AIR-22-03)	R44_SL-81 134	INSP		3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M 24*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
Tail Rotor Blade Condition and Care	R44_SL-82A 135	INSP		3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M 24*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
Perform EASA SIB No.: 2013-04R1 - Hook and Loop Style Fasteners as Mounting Mechanism for an Emergency Locator Transmitter	EASA_SIB_2 013-04R1; KANNAD_S B_S1800000 -25 136	INSP		3751:06	24.05.2023	3474:18	12MO	15DY	7MO*	08.06.2024*	24 May 2024+15DY*	193DY
Tail Rotor Blade Inspection C029-3	R44_SB-112_PART-A 136	INSP		3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M 24*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
Critical Tasks: The Maintenance Organization has to follow the manufacturer instructions and regulations acc. Part-M/ML and Part-145.	150	INSP		3751:06	21.09.2023	3681:36	100FH / 12MO	10FH/15 DY	40:30FH*/11M 24*	3791:36FH*/06.10.2024*	3781:36+10FH* / 21 Sep 2024+15DY*	40:30FH / 313DY
D-HUBI only: GTR225B Annual Inspection acc. Air Alliance ICA 2016_006_R-44_0507 Rev. 1, Chapter 6	183	INSP		3751:06	24.05.2023	3474:18	12MO	15DY	7MO*	08.06.2024*	24 May 2024+15DY*	193DY
Kannad AF-Compact - 6 Years Inspection (together with Battery replacement) acc. Kannad SL S1840501-25-05, current revision	186	INSP		3751:06	30.06.2022		72MO		55MO	30.06.2028	30 Jun 2028	1676DY
Kannad AF-Compact - Annual Inspection acc. Kannad SL S1840501-25-05, current revision	187	INSP		3751:06	24.05.2023	3474:18	12MO	15DY	7MO*	08.06.2024*	24 May 2024+15DY*	193DY
Scheduled Engine Engine	200	INSP		3751:06								
LYC § 04.4 - 50-Hour Inspection	204	INSP		3751:06	12.10.2023	3714:06	50±10FH		22:06FH	3773:12FH	3773:12±10FH	22:06±10FH
LYC § 04.5 - 100-Hour Inspection	205	INSP		3751:06	21.09.2023	3681:36	100FH	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
LYC § 04.6 - 400-Hour Inspection (Shorter Intervall)	206	INSP		3751:06	24.05.2023	3474:18	100FH 300FH	15FH	38:12FH*	3789:18FH*	3774:18+15FH*	38:12FH
LYC SI-1129D - Method of checking DC Alternator Belt Tension	207	INSP		3751:06	21.09.2023	3681:36	100FH	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
LYC SI-1191A - Cylinder Compression	208	INSP		3751:06	21.09.2023	3681:36	100FH	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
LYC SI-1080C - Maintenance Items for special attention	209	INSP		3751:06	12.10.2023	3714:06	50±10FH		22:06FH	3773:12FH	3773:12±10FH	22:06±10FH
LYC SB-301C - Maintenance Procedure and Service Limitation for Valves	210	INSP		3751:06	24.05.2023	3474:18	100FH 300FH	15FH	38:12FH*	3789:18FH*	3774:18+15FH*	38:12FH
LYC SB-366C - Carburetor Throttle Body Screw Inspection	212	INSP		3751:06	12.10.2023	3714:06	50±10FH / 12MO±15DY		22:06FH/11M O	3773:12FH/12.10.2024	3773:12±10FH / 12 Oct 2024+15DY	22:06±10FH / 319±15DY
LYC SB-388C / EU-2005-0023 R3 / LTA HB-2006-330 - Procedure to Determine Exhaust Valve and Guide Condition	EU-2005-002 3R3; LYC_SB-388 C 213	INSP		3751:06	24.05.2023	3474:18	100FH 330FH		53:12FH	3804:18FH	3804:18FH	53:12FH
Perform LYC SB-480F - (and R44 SL-83, as applicable) I. Oil & Filter Change & Screen Cleaning / II. Oil Filter/Screen Content Inspection. NOTE: Oil filters on D723-1 adapters do not require safety wire.	LYC_MSB-4 80F 215	INSP		3751:06	12.10.2023	3714:06	25FH 50±10FH / 4MO±15DY		22:06FH/3MO	3773:12FH/12.02.2024	3773:12±10FH / 12 Feb 2024+15DY	22:06±10FH / 76±15DY
LYC SB-183A - Magneto Timing Discrepancies	216	INSP		3751:06	21.09.2023	3681:36	100FH	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
Scheduled Maintenance LH Magneto	250	INSP		3751:06								
CMI SB-643C - LH Magneto 100 Hours/Annual	252	INSP	BL-600616-3 E15HA084 R	3751:06	21.09.2023	3681:36	100FH / 12MO	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
CMI SB-643C - LH Magneto 500 Hours	254	INSP	BL-600616-3 E15HA084 R	3751:06	01.08.2023	3578:54	500FH / 48MO	25FH/30 DY	352:48FH*/45 MO*	4103:54FH*/31.08.2027*	4078:54+25FH* / 01 Aug 2027+30DY*	352:48FH / 1372DY
Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - LH Magneto	262	INSP		3751:06	01.08.2023	3578:54	500FH / 48MO	25FH/30 DY	352:48FH*/45 MO*	4103:54FH*/31.08.2027*	4078:54+25FH* / 01 Aug 2027+30DY*	352:48FH / 1372DY

D-HUBI - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3751:06	TSO: 1715:36	
Hobbs: 3751:06	Pn: O-540-F1B5	
Type: R44	Sn: L-26650-40A	
Sn: 0725		

Description	AD/SB/MOD IATA / 1	Action Pn	Sn	Curr. FH	Start date Ac. TT LSV TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT			
Scheduled Maintenance RH Magneto					280						3751:06			
CMI SB-643C - RH Magneto 100 Hours/Annual		282	INSP	10-600646-201	G-04547	3751:06	21.09.2023	3681:36	100FH / 12MO	10FH	40:30FH*	3791:36FH*	3781:36+10FH*	40:30FH
CMI SB-643C - RH Magneto 500 Hours		284	INSP	10-600646-201	G-04547	3751:06	01.08.2023	3578:54	500FH / 48MO	25FH/30 DY	352:48FH*/45 MO*	4103:54FH*/31.08.2027*	4078:54+25FH* / 01 Aug 2027+30DY*	352:48FH / 1372DY
CMI SB-663A Two-Wire Magneto Tach. Breaker Contact (Points) Assy. P/N 10-400507 - RH Magneto Model S4LSC-204T (P/N 10-600644-201, BL-600644-201) and S6LSC-204T (P/N 10-600646-201, BL-600646-201)		288	INSP	10-600646-201	G-04547	3751:06	01.08.2023	3578:54	500FH / 48MO	25FH/30 DY	352:48FH*/45 MO*	4103:54FH*/31.08.2027*	4078:54+25FH* / 01 Aug 2027+30DY*	352:48FH / 1372DY
Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - RH Magneto		292	INSP			3751:06	01.08.2023	3578:54	500FH / 48MO	25FH/30 DY	352:48FH*/45 MO*	4103:54FH*/31.08.2027*	4078:54+25FH* / 01 Aug 2027+30DY*	352:48FH / 1372DY
Fatigue Life Limited Parts/Overhaul/Additional Component Maintenance		300	LL			3751:06								
Main Rotor Blade		306	LL	C016-7	6800 REV.AH	3751:06	24.02.2016	3323:12	2200FH / 144MO		1149:54FH/51 MO	4901FH/24.02.2028	4901FH / 24 Feb 2028	1149:54FH / 1549DY
Main Rotor Blade		307	LL	C016-7	6804 REV.AH	3751:06	24.02.2016	3323:12	2200FH / 144MO		1149:54FH/51 MO	4901FH/24.02.2028	4901FH / 24 Feb 2028	1149:54FH / 1549DY
Upper Frame		308	LL	C020-1	9837 REV.W	3751:06	03.04.2019	2244:00	2200FH		692:54FH	4444FH	4444FH	692:54FH
Tail Rotor Blade		314	LL	C029-3	1070 REV.N	3751:06	15.10.2012	2035:30	2200FH / 144MO		382:24FH/11 MO	4133:30FH/15.10.2024	4133:30FH / 15 Oct 2024	382:24FH / 322DY
Tail Rotor Blade		315	LL	C029-3	1174 REV.N	3751:06	15.10.2012	2035:30	2200FH / 144MO		382:24FH/11 MO	4133:30FH/15.10.2024	4133:30FH / 15 Oct 2024	382:24FH / 322DY
Gear Set, Main Gearbox		319	LL	C146-5	8900 REV.N	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Main Rotor Hub		321	LL	C154-1	10896W	3751:06	30.11.2018	2237:54	2200FH		686:48FH	4437:54FH	4437:54FH	686:48FH
Main Rotor Spindle		322	LL	C158-1	20149 REV.V	3751:06	22.09.2022	3323:12	2200FH		1149:54FH	4901FH	4901FH	1149:54FH
Main Rotor Spindle		323	LL	C158-1	20151 REV.V	3751:06	22.09.2022	3323:12	2200FH		1149:54FH	4901FH	4901FH	1149:54FH
Sump, Main Gearbox		326	LL	C263-2	6532 REV.H	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Housing, Main Gearbox		328	LL	C264-2	9038 REV.L	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Gear Set, Tail Gearbox		329	LL	C545-1	9705 REV.J	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Bearing Set, C017-6 Swashplate		331	LL	C647-12	B162058	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Tail Rotor Guard		333	LL	D079-1	10258 REV.V	3751:06	28.12.2016	2035:30	2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Tail Rotor Hub		334	LL	G062-2	3594 REV.E	3751:06	28.12.2016	2035:30	2200FH		382:24FH	4133:30FH	4133:30FH	382:24FH
Tailcone Assembly, Rev N & Subsequ.		336	LL	C023-1	0817 REV.AA	3751:06	27.01.2020	0:00	4400FH		648:54FH	4400FH	4400FH	648:54FH
Horizontal Stabilizer, Rev. M & Subsequ.		342	LL	C044-1	4327	3751:06	10.11.2021	2920:54	4400FH		1369:48FH	5120:54FH	5120:54FH	1369:48FH
Lower Swashplate		343	LL	C198-1	0811	3751:06	27.01.2020	0:00	4400FH		648:54FH	4400FH	4400FH	648:54FH
Main Rotor Shaft		345	LL	C251-2	R4116 REV.M	3751:06	28.12.2016	0:00	4400FH		648:54FH	4400FH	4400FH	648:54FH
Cyclic Torque Tube		346	LL	C319-3	0762	3751:06	27.01.2020	0:00	4400FH		648:54FH	4400FH	4400FH	648:54FH
Tail Rotor Drive Shaft		349	LL	D196-1	7595 REV.H	3751:06	28.12.2016	2035:30	4400FH		2684:24FH	6435:30FH	6435:30FH	2684:24FH

D-HUBI - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3751:06	TSO: 1715:36	
Hobbs: 3751:06	Pn: O-540-F1B5	
Type: R44	Sn: L-26650-40A	
Sn: 0725		

Description	AD/SB/MOD	ATA / 1	Action	Pn	Sn	Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
Tail Rotor Bellcrank	350	TBO	A120-3			3751:06	28.12.2016	2035:30			144MO		61MO	28.12.2028	28 Dec 2028	1857DY
Tail Rotor Bellcrank	351	OTL	A120-3			3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Oil lines	354	OC	A723-15	REV.W		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Oil lines	355	OC	A723-16	REV.U		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Main Rotor Blade and Spindle Assy	369	TBO	C005-12	REV.V		3751:06	22.09.2022	3323:12			2200FH		1149:54FH	4901FH	4901FH	1149:54FH
Main Rotor Blade and Spindle Assy	370	INSP	C005-12	REV.V		3751:06	24.02.2016	3323:12			144MO		51MO	24.02.2028	24 Feb 2028	1549DY
Main Rotor Hub Assy	371	INSP	C005-x			3751:06	28.12.2016	2035:30			144MO		61MO	28.12.2028	28 Dec 2028	1857DY
Main Rotor Gearbox and Mast Assy	372	TBO	C006-8	3392 REV.AJ		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Main Rotor Gearbox and Mast Assy	373	INSP	C006-8	3392 REV.AJ		3751:06	29.08.2016	2035:30			144MO		57MO	29.08.2028	29 Aug 2028	1736DY
Fanshaft and Bearing Assy	374	TBO	C007-5	8541 REV.AA		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Fanshaft and Bearing Assy	375	INSP	C007-5	8541 REV.AA		3751:06	30.08.2016	2035:30			144MO		57MO	30.08.2028	30 Aug 2028	1737DY
Tail Rotor Assy	376	TBO	C008-9			3751:06	28.12.2016	2035:30			2200FH		382:24FH	4133:30FH	4133:30FH	382:24FH
Tail Rotor Assy	377	INSP	C008-9			3751:06	05.04.2016	2035:30			144MO		53MO	05.04.2028	05 Apr 2028	1590DY
Swashplate Assy	379	TBO	C017-6	3440 REV.AE		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Swashplate Assy	380	INSP	C017-6	3440 REV.AE		3751:06	30.08.2016	2035:30			144MO		57MO	30.08.2028	30 Aug 2028	1737DY
Clutch Assy	381	TBO	C018-2			3751:06	21.09.2023	3668:17			2200±50FH		507:35FH	4258:41FH	4258:41±50FH	507:35±50FH
Clutch Assy	382	INSP	C018-2			3751:06	29.10.2014	3676:42			144MO		35MO	29.10.2026	29 Oct 2026	1066DY
Tail Rotor Gearbox Assy	383	TBO	C021-1	8187 REV.P		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Tail Rotor Gearbox Assy	384	INSP	C021-1	8187 REV.P		3751:06	30.08.2016	2035:30			144MO		57MO	30.08.2028	30 Aug 2028	1737DY
Tail Rotor Pitch Control	386	TBO	C031-1	9757 REV.K		3751:06	30.08.2016	2035:30			2200FH / 144MO		484:24FH/57MO	4235:30FH/30.08.2028	4235:30FH / 30 Aug 2028	484:24FH / 1737DY
Belt Tension Actuator Assy	388	TBO	C051-1	2201 REV.T		3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Belt Tension Actuator Assy	389	INSP	C051-1	2201 REV.T		3751:06	09.08.2016	2035:30			144MO		57MO	09.08.2028	09 Aug 2028	1716DY
Spring Assy	390	TBO	C056-1			3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Harness & Buckle Assy	399	TBO	C628-x			3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Harness & Buckle Assy	400	TBO	C628-x			3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Harness & Buckle Assy	401	TBO	C628-x			3751:06	28.12.2016	2035:30			2200FH		484:24FH	4235:30FH	4235:30FH	484:24FH
Mount	402	TBO	C653-1	REV. J		3751:06	22.07.2018	2615:00			144MO		80MO	22.07.2030	22 Jul 2030	2428DY
Mount	403	TBO	C653-2	REV. H		3751:06	24.01.2017	2615:00			144MO		62MO	24.01.2029	24 Jan 2029	1884DY

D-HUBI - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3751:06	TSO: 1715:36	
Hobbs: 3751:06	Pn: O-540-F1B5	
Type: R44	Sn: L-26650-40A	
Sn: 0725		

Description	AD/SB/MOD IATA / 1	Action Pn	Sn	Curr. FH	Start date Ac. TT LSV TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT	
Dual Tachometer	404	INSP C792-4	486 REV.J	3751:06	29.08.2016	2035:30	144MO	57MO	29.08.2028	29 Aug 2028	1736DY	
Fanwheel Assy	409	TBO D174-2	REV.QL	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Fanwheel Assy	410	INSP D174-2	REV.QL	3751:06	15.08.2016	2035:30	144MO	57MO	15.08.2028	15 Aug 2028	1722DY	
Hydraulic Reservoir	411	TBO D211-1	2238 REV.I	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Hydraulic Reservoir	412	INSP D211-1	2238 REV.I	3751:06	28.12.2016	2035:30	144MO	61MO	28.12.2028	28 Dec 2028	1857DY	
Hydraulic Servo Actuators	413	TBO D212-1	6549	3751:06	30.11.2018	2237:54	2200FH	686:48FH	4437:54FH	4437:54FH	686:48FH	
Hydraulic Servo Actuators	413	INSP D212-1	6549	3751:06	15.10.2018	2237:54	144MO	83MO	15.10.2030	15 Oct 2030	2513DY	
Hydraulic Servo Actuators	414	TBO D212-1	3006 REV.P/3005 REV.P	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Hydraulic Servo Actuators	414	INSP D212-1	3006 REV.P/3006 REV.P	3751:06	01.09.2016	2035:30	144MO	58MO	01.09.2028	01 Sep 2028	1739DY	
Tail Rotor Drive Shaft	415	OTL D224-2	7595 REV.L	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Governor Controller Assy	416	TBO D278-1	1506 REV.E	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Governor Controller Assy	417	INSP D278-1	1506 REV.E	3751:06	07.06.2016	2035:30	144MO	55MO	07.06.2028	07 Jun 2028	1653DY	
Clutch Shaft	420	TBO C166-4	0421	3751:06	21.09.2023	3676:42	2200±50FH	507:35FH	4258:41FH	4258:41±50FH	507:35±50FH	
Clutch Shaft	421	INSP C166-4	0421	3751:06	29.10.2014	3676:42	144MO	35MO	29.10.2026	29 Oct 2026	1066DY	
Bearing Assy	422	TBO C181-3	8541	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Bearing Assy	423	INSP C181-3	8541	3751:06	28.12.2016	2035:30	144MO	61MO	28.12.2028	28 Dec 2028	1857DY	
Sprag Clutch	424	TBO C188-3	11543	3751:06	21.09.2023	3676:42	2200±50FH	507:35FH	4258:41FH	4258:41±50FH	507:35±50FH	
Sprag Clutch	425	INSP C188-3	11543	3751:06	29.10.2014	3676:42	144MO	35MO	29.10.2026	29 Oct 2026	1066DY	
Hydraulic Pump	426	TBO D500-1	1645 REV.F	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Main Rotor Drive Shaft	427	OH C251-2	R4116 REV.M	3751:06	28.12.2016	2035:30	2200FH	484:24FH	4235:30FH	4235:30FH	484:24FH	
Engine Overhaul	600			3751:06								
Engine	601	OH O-540-F1B5	L-26650-40A	3751:06	25.08.2016	2035:30	2000FH / 144MO	200FH	484:24FH*/57MO	4235:30FH*/25.08.2028	4035:30+200FH* / 25 Aug 2028	484:24FH / 1732DY
Magneto LH	603	OH BL-600616-3	E15HA084R	3751:06	16.05.2023	3578:54	2000FH / 144MO	200FH	2027:48FH*/138MO	5778:54FH*/16.05.2035	5578:54+200FH* / 16 May 2035	2027:48FH / 4187DY
Magneto RH	604	OH 10-600646-201	G-04547	3751:06	25.01.2023	3578:54	2000FH / 144MO	200FH	2027:48FH*/134MO	5778:54FH*/25.01.2035	5578:54+200FH* / 25 Jan 2035	2027:48FH / 4076DY
Carburetor	605	OH 10-6035-11	MSC03503	3751:06	25.08.2016	2035:30	2000FH	200FH	484:24FH*	4235:30FH*	4035:30+200FH*	484:24FH
Starter	606	OH BC315-100-2	2A00N7W78	3751:06	29.10.2021	2908:48	2000FH	200FH	1357:42FH*	5108:48FH*	4908:48+200FH*	1357:42FH
Alternator	608	OH ALX-8521R	H-T040928	3751:06	21.09.2023	3676:42	2000FH	200FH	1507:18FH*	5258:24FH*	5058:24+200FH*	1507:18FH

D-HUBI - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3751:06	TSO: 1715:36	
Hobbs: 3751:06	Pn: O-540-F1B5	
Type: R44	Sn: L-26650-40A	
Sn: 0725		

Description	AD/SB/MOD IATA / 1 Action Pn	Sn	Curr. FH	Start date Ac. TT LSV TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT	
Oil Cooler	612 OH 10886A (C0649-2)	1127	3751:06	16.06.2023	3520:54	2000FH	20FH	1789:48FH*	5540:54FH*	5520:54+20FH*	1789:48FH
Additional Requirements	650		3751:06								
ELT Battery	651 LL ALL		3751:06	30.06.2022	2938:54	72MO	55MO	30.06.2028	30 Jun 2028	1676DY	
Fire Extinguisher	653 LL RT-A400 X-718972		3751:06	31.12.2022		144MO	13MO	31.12.2024	31 Dec 2024	399DY	
First Aid Kit	655 LL		3751:06	30.04.2019	2992:12	60MO	5MO	30.04.2024	30 Apr 2024	154DY	
Check that current POH Revision is installed	656 INSP		3751:06	21.04.2023	3424:48	12MO	15DY	6MO*	06.05.2024*	21 Apr 2024+15DY*	160DY
Check that current Pilot Checklist is installed	657 INSP		3751:06	21.04.2023	3424:48	12MO	15DY	6MO*	06.05.2024*	21 Apr 2024+15DY*	160DY