

## D-HORS - Recurring Maintenance (All)

<b>Aircraft</b>	<b>Engine(s)</b>	<b>1</b>
TT: <b>1512:12</b>	TSO: <b>1512:12</b>	
Hobbs: <b>1512:12</b>	Pn: <b>IO-540-AE1A5</b>	
Type: <b>R44 II</b>	Sn: <b>L-29961-48A</b>	
Sn: <b>10682</b>		

Description	AD/SB/MOD No.	ATA / Tas Action	Pn	Sn		Curr. FH	Start date	Ac. TT LSV	TH	Int.	Ext.*	Rem.	Due
European Requirements		000				1512:12							
Full Airworthiness Review		001	INSP			1512:12	07.07.2023	1512:12		36MO		36MO	07.07.2026
ARC Extension		002	INSP			1512:12	07.07.2023	1512:12		12MO		12MO	07.07.2024
EASA SIB 2011-15R2 - Mode S Transponder Check		003	INSP			1512:12	15.11.2021	1511:54		24MO	30DY	5MO*	15.12.2023*
Compass Compensation acc. FAR 23.1547 & 23.1327		006	INSP			1512:12	05.07.2023	1512:12		24MO	30DY	25MO*	04.08.2025*
First Aid Kit		008	INSP			1512:12	05.07.2023	1512:12		12MO	15DY	12MO*	20.07.2024*
Perform Weight & Balance (AMC1 CAT.POL.MAB.100(b)) and replace POH W&B Report & Equipmentlist		009	INSP			1512:12	22.09.2020			48MO	30DY	15MO*	22.10.2024*
RHC § 2.600 - 2200-hour inspection (R44 / R44 II)		101a	INSP			1512:12	29.03.2005	0:00		2200FH		687:48FH	2200FH
RHC § 2.600 - 12-Year inspection		102	INSP			1512:12	15.09.2016	1321:24		144MO		62MO	15.09.2028
RHC § 2.200 - Ground & Flight Check for 100hour/Annual Inspection		103a	INSP			1512:12	07.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/22.07.2024*
RHC § 2.300 - Airframe Preparation for 100-Hour/Annual Inspection		103b	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC § 2.400 - 100-hour/Annual Airframe Inspection		104	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC § 7.210 - Perform clutch assembly lubricant inspection & servicing		105	INSP			1512:12	05.07.2023	1512:12		500FH	25FH	525FH*	2037:12FH*
RHC § 1.120 - Drain and flush MGB		108	INSP			1512:12	05.07.2023	1512:12		500FH	25FH	525FH*	2037:12FH*
RHC § 1.130 - Drain and flush TGB		109	INSP			1512:12	05.07.2023	1512:12		500FH	25FH	525FH*	2037:12FH*
RHC § 1.115 - Clean gearbox chip detectors		110	INSP			1512:12	05.07.2023	1512:12		500FH / 12MO	25FH/15DY	525FH*/12MO*	2037:12FH*/20.07.2024*
RHC § 1.140 - Lubricate C181-3 bearings		111	INSP			1512:12	05.07.2023	1512:12		300FH / 36MO	15FH/30DY	315FH*/37MO*	1827:12FH*/04.08.2026*
RHC § 1.140 - Perform Ground Run after bearing lubrication		112	INSP			1512:12	05.07.2023	1512:12		300FH / 36MO	15FH/30DY	315FH*/37MO*	1827:12FH*/04.08.2026*
RHC § 1.170 - Replace hydraulic filter		113	INSP			1512:12	05.07.2023	1512:12		300FH	15FH	315FH*	1827:12FH*
RHC § 12-83 - Perform pressure relief valve leakage check (R44 II)		114	INSP			1512:12	05.07.2023	1512:12		12MO	15DY	12MO*	20.07.2024*
RHC SL-38 - Cracked MS2142L-Nuts Inspection		122	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC SL-43 - C343-1 Push-Pull Tube Inspection		123	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC SL-50 - D210 Corrosion-Resistant (CRES) Nuts		126	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC SL-64A - Fire Extinguisher Handling & Maintenance P/N B381- (RT-A400)		127	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC § 28-60 (RHC SL-70) - Main Rotor Blade Tip Maintenance		128	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
RHC SL-48 / Precision Airmotive SB PRS-109 Rev.1 - Idle Valve Thrust Washer Wear on Robinson R44 II Helicopters	R44_SL-48	129	INSP			1512:12	05.07.2023	1512:12		500FH	25FH	525FH*	2037:12FH*
ELT Security (FAA SAIB AIR-22-03)	R44_SL-81	130	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
Tail Rotor Blade Condition and Care	R44_SL-82A	131	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*
Tail Rotor Blade Inspection C029-3	R44_SB-112_PART-A	132	INSP			1512:12	05.07.2023	1512:12		100FH / 12MO	10FH/15DY	110FH*/12MO*	1622:12FH*/20.07.2024*

## D-HORS - Recurring Maintenance (All)

Aircraft	Engine(s)											
TT: 1512:12	TSO: 1512:12											
Hobbs: 1512:12	Pn: IO-540-AE1A5											
Type: R44 II	Sn: L-29961-48A											
Sn: 10682												
Description	AD/SB/MOD No.	ATA / Tas Action	Pn	Sn	Curr. FH	Start date	Ac. TT LSV	TH	Int.	Ext.*	Rem.	Due
Perform EASA SIB No.: 2013-04R1 - Hook and Loop Style Fasteners as Mounting Mechanism for an Emergency Locator Transmitter	EASA_SIB_2013-04R1; KANNAD_SB_S1800000-25	134	INSP		1512:12	05.07.2023	1512:12		12MO	15DY	12MO*	20.07.2024*
Kannad AF-Compact - 6 Years Inspection (together with Battery replacement) acc. Kannad SL S1840501-25-05, current revision		186	INSP		1512:12	30.04.2023	1512:12		72MO		69MO	30.04.2029
Kannad AF-Compact - Annual Inspection acc. Kannad SL S1840501-25-05, current revision		187	INSP		1512:12	27.06.2023	1512:12		12MO	15DY	12MO*	12.07.2024*
LYC § 04.4 - 50-Hour Inspection		204	INSP		1512:12	05.07.2023	1512:12		50FH	10FH	60FH*	1572:12FH*
LYC § 04.5 - 100-Hour Inspection		205	INSP		1512:12	05.07.2023	1512:12		100FH	10FH	110FH*	1622:12FH*
LYC § 04.6 - 400-Hour Inspection (Shorter Interval)		206	INSP		1512:12	05.07.2023	1512:12	100FH	300FH	30FH	330FH*	1842:12FH*
LYC SI-1129D - Method of checking DC Alternator Belt Tension		207	INSP		1512:12	05.07.2023	1512:12		100FH	10FH	110FH*	1622:12FH*
LYC SI-1191A - Cylinder Compression		208	INSP		1512:12	05.07.2023	1512:12		100FH	10FH	110FH*	1622:12FH*
LYC SI-1080C - Maintenance Items for special attention		209	INSP		1512:12	05.07.2023	1512:12		50FH	10FH	60FH*	1572:12FH*
LYC SB-301C - Maintenance Procedure and Service Limitation for Valves		210	INSP		1512:12	05.07.2023	1512:12	100FH	300FH	30FH	330FH*	1842:12FH*
LYC SB-342G / AD US-2015-19-07 - Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation (IO-540 only) - Note: 100hrs Requirement to 50hrs reduced due to no tolerance to the AD.	US-2015-19-07; LYC_MSB-342G	211	INSP		1512:12	05.07.2023	1512:12		50FH	10FH	60FH*	1572:12FH*
LYC SB-388C / EU-2005-0023 R3 / LTA HB-2006-330 - Procedure to Determine Exhaust Valve and Guide Condition	EU-2005-0023R3; LYC_SB-388C	213	INSP		1512:12	05.07.2023	1512:12	100FH	330FH		330FH	1842:12FH
Perform LYC SB-480F - (and R44 SL-83, as applicable) I. Oil & Filter Change & Screen Cleaning / II. Oil Filter/Screen Content Inspection. NOTE: Oil filters on D723-1 adapters do not require safety wire.	LYC_MSB-480F	215	INSP		1512:12	05.07.2023	1512:12	25FH	50FH / 4MO	10FH/15DY	60FH*/4MO*	1572:12FH*/20.11.2023*
LYC SB-183A - Magneto Timing Discrepancies		216	INSP		1512:12	05.07.2023	1512:12		100FH	10FH	110FH*	1622:12FH*
CMI SB-643C - LH Magneto 100 Hours		252	INSP		1512:12	10.09.2021	1511:54		100FH	10FH	109:42FH*	1621:54FH*
CMI SB-643C - LH Magneto 500 Hours		254	INSP	10-600616-9	E06KA559	05.07.2023	1512:12		500FH / 48MO	25FH/30DY	525FH*/49MO*	2037:12FH*/04.08.2027*
CMI SB-670 Replacement and maintenance of Magneto Distributer Block - LH Magneto		260	INSP	10-600616-9	E06KA559	05.07.2023	1512:12		500FH / 48MO	25FH/30DY	525FH*/49MO*	2037:12FH*/04.08.2027*
CMI SB-658 - 100 Hour Distributer Gear Maintenance - LH Magneto		261	INSP		1512:12	10.09.2021	1511:54		100FH	10FH	109:42FH*	1621:54FH*
CMI SB-643C - RH Magneto 100 Hours		282	INSP		1512:12	10.09.2021	1511:54		100FH	10FH	109:42FH*	1621:54FH*
CMI SB-643C - RH Magneto 500 Hours		284	INSP	10-600646-201	E03LA020	05.07.2023	1512:12		500FH / 48MO	25FH/30DY	525FH*/49MO*	2037:12FH*/04.08.2027*
CMI SB-658 - 500 Hours/48 months Distributer Gear Maintenance - RH Magneto		286	INSP	10-600646-201	E03LA020	05.07.2023	1512:12		500FH / 48MO	30DY	500FH/49MO*	2012:12FH/04.08.2027*
CMI SB-663A Two-Wire Magneto Tach. Breaker Contact (Points) Assy. P/N 10-400507 - RH Magneto		288	INSP	10-600646-201	E03LA020	05.07.2023	1512:12		500FH / 48MO	25FH/30DY	525FH*/49MO*	2037:12FH*/04.08.2027*
CMI SB-670 Replacement and maintenance of Magneto Distributer Block - LH Magneto		290	INSP	10-600646-201	E03LA020	05.07.2023	1512:12		500FH / 48MO	25FH/30DY	525FH*/49MO*	2037:12FH*/04.08.2027*
CMI SB-658 - 100 Hour Distributer Gear Maintenance - RH Magneto		291	INSP		1512:12	10.09.2021	1511:54		100FH	10FH	109:42FH*	1621:54FH*
Fatigue Life Limited Parts/Overhaul/Additional Component Maintenance		300	LL		1512:12							
Main Rotor Blade		306	LL	C016-7	7043 REV.AH	08.04.2016	1321:24		2200FH / 144MO		2009:12FH/57MO	3521:24FH/08.04.2028

## D-HORS - Recurring Maintenance (All)

<b>Aircraft</b>	<b>Engine(s)</b>	<b>1</b>
TT: <b>1512:12</b>	TSO: <b>1512:12</b>	
Hobbs: <b>1512:12</b>	Pn: <b>IO-540-AE1A5</b>	
Type: <b>R44 II</b>	Sn: <b>L-29961-48A</b>	
Sn: <b>10682</b>		

Description	AD/SB/MOD No.	ATA / Tas Action	Pn	Sn	Curr. FH	Start date	Ac. TT LSV TH	Int.	Ext.*	Rem.	Due
Main Rotor Blade		307 LL	C016-7	7038 REV.AH	1512:12	08.04.2016	1321:24	2200FH / 144MO		2009:12FH/57MO	3521:24FH/08.04.2028
Upper Frame		308 LL	C020-1	2409	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Tail Rotor Blade		313 LL	C029-2	5677 REV.O	1512:12	15.09.2016	1321:24	2200FH / 144MO		2009:12FH/62MO	3521:24FH/15.09.2028
Tail Rotor Blade		314 LL	C029-3	5670 REV.O	1512:12	15.09.2016	1321:24	2200FH / 144MO		2009:12FH/62MO	3521:24FH/15.09.2028
Gear Set, Main Gearbox		319 LL	C146-5	8858 REV.N	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Main Rotor Hub		321 LL	C154-1	2441 REV.E	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Main Rotor Spindle		322 LL	C158-1	20408 REV.J	1512:12	08.04.2016	1321:24	2200FH		2009:12FH	3521:24FH
Main Rotor Spindle		323 LL	C158-1	20401 REV.J	1512:12	06.04.2016	1321:24	2200FH		2009:12FH	3521:24FH
Sump, Main Gearbox		326 LL	C263-2	6438 REV.H	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Housing, Main Gearbox		328 LL	C264-2	8931 REV.L	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Gear Set, Tail Gearbox		329 LL	C545-1	2787 REV.G	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Bearing Set, C017-6 Swashplate		331 LL	C647-12	D162039 REV.AB	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Tail Rotor Guard		333 LL	D079-1	2635 REV.T	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Tail Rotor Hub		334 LL	G062-2	3669 REV.E	1512:12	15.03.2016	1321:24	2200FH		2009:12FH	3521:24FH
Tailcone Assembly, Rev N & Subsequ.		336 LL	C023-1	2400 REV.AH	1512:12	29.03.2005	0:00	4400FH		2887:48FH	4400FH
Horizontal Stabilizer, Rev. M & Subsequ.		342 LL	C044-1	2419 REV.Q	1512:12	29.03.2005	0:00	4400FH		2887:48FH	4400FH
Lower Swashplate		344 LL	C198-2	2513 REV.M	1512:12	29.03.2005	0:00	4400FH		2887:48FH	4400FH
Tail Rotor Drive Shaft		349 LL	D196-1	0507	1512:12	29.03.2005	0:00	4400FH		2887:48FH	4400FH
Tail Rotor Bellcrank		350 TBO	A120-3	REV.P	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
V-belts		352 TBO	A190-3	REV.AA	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hoses, Air Ducts		358 TBO	A785-31	REV.AW	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hoses Assys		365 TBO	B283-x		1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Main Rotor Blade and Spindle Assy		369 TBO	C005-12	REV.V	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Main Rotor Blade and Spindle Assy		370 INSP	C005-12	REV.V	1512:12	08.04.2016	1321:24	144MO		57MO	08.04.2028
Main Rotor Hub Assy		371 INSP	C005-4	REV.V	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Main Rotor Gearbox and Mast Assy		372 TBO	C006-7	1271 REV.AJ	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Main Rotor Gearbox and Mast Assy		373 INSP	C006-7	1271 REV.AJ	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Fanshaft and Bearing Assy		374 TBO	C007-5	8372 REV.AA	1512:12	15.09.2016	1321:42	2200FH		2009:30FH	3521:42FH
Fanshaft and Bearing Assy		375 INSP	C007-5	8372 REV.AA	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Tail Rotor Assy		376 TBO	C008-9		1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Tail Rotor Assy		377 INSP	C008-9		1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Swashplate Assy		379 TBO	C017-4	2365 REV.W	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Swashplate Assy		380 INSP	C017-4	2365 REV.W	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028

## D-HORS - Recurring Maintenance (All)

<b>Aircraft</b>	<b>Engine(s)</b>	<b>1</b>
TT: <b>1512:12</b>	TSO: <b>1512:12</b>	
Hobbs: <b>1512:12</b>	Pn: <b>IO-540-AE1A5</b>	
Type: <b>R44 II</b>	Sn: <b>L-29961-48A</b>	
Sn: <b>10682</b>		

Description	AD/SB/MOD No.	ATA / Tas Action	Pn	Sn	Curr. FH	Start date	Ac. TT LSV TH	Int.	Ext.*	Rem.	Due
Clutch Assy		381 TBO	C018-2		1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Clutch Assy		382 INSP	C018--2		1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Tail Rotor Gearbox Assy		383 TBO	C021-1	2318 REV.J	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Tail Rotor Gearbox Assy		384 INSP	C021-1	2318 REV.V	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Tail Rotor Pitch Control		386 TBO	C031-1	9571 REV.K	1512:12	15.09.2016	1321:24	2200FH / 144MO		2009:12FH/62MO	3521:24FH/15.09.2028
Belt Tension Actuator Assy		388 TBO	C051-2	5811 REV.W	1512:12	15.09.2010	907:30	2200FH		1595:18FH	3107:30FH
Belt Tension Actuator Assy		389 INSP	C051-2	5811 REV.W	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Swashplate Boot		394 TBO	C480-1	REV.B	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Mount		402 TBO	C653-1	REV.G	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Mount		403 TBO	C653-2	REV.G	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Dual Tachometer		404 TBO	C792-4	1063	1512:12	04.10.2012	1406:12	144MO		15MO	04.10.2024
Fanwheel Assy		409 TBO	D174-2		1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Fanwheel Assy		410 INSP	D174-2		1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hydraulic Reservoir		411 TBO	D211-2	4732 REV.L	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Hydraulic Reservoir		412 INSP	D211-2	4732 REV.L	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hydraulic Servo Actuators		413 TBO	D212-1	4591A / 4592	1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Hydraulic Servo Actuators		413 INSP	D212-1	4591A / 4592	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hydraulic Servo Actuator		414 TBO	D212-1	5398	1512:12	05.09.2005	50:18	2200FH		738:06FH	2250:18FH
Hydraulic Servo Actuator		414 INSP	D121-1	5398	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Governor Controller Assy		416 TBO	D278-2	2124 REV.E	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Governor Controller Assy		417 INSP	D278-2	2124 REV.E	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Bellcrank Assy		418 TBO	D756-3	REV.F	1512:12	15.06.2019	1321:24	144MO		95MO	15.06.2031
Clutch Shaft		420 TBO	C166-4	10018 REV.P	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Clutch Shaft		421 INSP	C166-4	10018 REV.P	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Bearing Assy		422 TBO	C181-3	8372 REV.J	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Bearing Assy		423 INSP	C181-3	8372 REV.J	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Sprag Clutch		424 TBO	C188-3	10914 REV.H	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Sprag Clutch		425 INSP	C188-3	10914 REV.H	1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
Hydraulic Pump		426 TBO	D500-1	6479 REV.I	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
Main Rotor Drive Shaft		427 OH	C251-2	R2217 REV.L	1512:12	15.09.2016	1321:24	2200FH		2009:12FH	3521:24FH
RHC § 1.102 A. Perform 12 Years Additional Component Maintenance		500			1512:12	15.09.2016	1321:24	144MO		62MO	15.09.2028
RHC § 1.102 B. Perform 2200/2400 Hours Additional Component Maintenance		510			1512:12	29.03.2005	0:00	2200FH		687:48FH	2200FH
Engine Overhaul		600			1512:12						

## D-HORS - Recurring Maintenance (All)

<b>Aircraft</b>	<b>Engine(s)</b>	<b>1</b>
TT: 1512:12	TSO: 1512:12	
Hobbs: 1512:12	Pn: IO-540-AE1A5	
Type: R44 II	Sn: L-29961-48A	
Sn: 10682		

Description	AD/SB/MOD No.	ATA / Tas Action	Pn	Sn		Curr. FH	Start date	Ac. TT LSV TH	Int.	Ext.*	Rem.	Due
Engine		602 OH	IO-540-AE1A5	L-29961-48A		1512:12	29.03.2005	0:00	2000FH / 144MO	200FH/2555DY	687:48FH*/8MO*	2200FH*/27.03.2024*
Magneto LH		603 OH	10-600616-9	E06KA559		1512:12	21.06.2021	1512:12	2000FH / 144MO	200FH	2200FH*/119MO	3712:12FH*/21.06.2033
Magneto RH		604 OH	10-600646-201	E03LA020		1512:12	01.06.2022	1512:12	2000FH / 144MO	200FH	2200FH*/131MO	3712:12FH*/01.06.2034
Starter		606 OH	BC315-100-4	1004241023		1512:12	29.03.2005	0:00	2000FH	200FH	687:48FH*	2200FH*
Alternator		607 OH	ALU-8521LS	E120111		1512:12	29.03.2005	0:00	2000FH	200FH	687:48FH*	2200FH*
Oil Cooler		610 OH	C649-2 (10599R)	4849		1512:12	29.03.2005	0:00	2200FH / 144MO	2555DY	687:48FH/8MO*	2200FH/27.03.2024*
Oil Cooler		611 OH	C649-3 (10886A)	1916		1512:12	29.03.2005	0:00	2200FH / 144MO	2555DY	687:48FH/8MO*	2200FH/27.03.2024*
Fuel Injector RSA-10AD1		615 OH	2576630-4	70761303		1512:12	29.03.2005	0:00	2000FH	200FH	687:48FH*	2200FH*
Additional Requirements		650				1512:12						
ELT Battery		651 LL	S1840510-01	TM0000270434		1512:12	30.04.2023	1512:12	72MO		69MO	30.04.2029
Fire Extinguisher		653 LL	RT-A400	H33368906		1512:12	31.12.2023	1512:12	144MO		149MO	31.12.2035
First Aid Kit		655 LL				1512:12	31.01.2022	1512:12	60MO		42MO	31.01.2027
Check that current POH Revision is installed		656 INSP				1512:12	05.07.2023	1512:12	12MO		12MO	05.07.2024
Check that current Pilot Checklist is installed		657 INSP				1512:12	05.07.2023	1512:12	12MO		12MO	05.07.2024