

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO: 1436:00	
Hobbs: 3498:30	Pn: O-540-F1B5	
Type: R44	Sn: L-26640-40A	
Sn: 1692		

Description	AD/SB/MOD	ATA / 1	Action	Pn	Sn	Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
European Requirements		000				3498:30										
Full Airworthiness Review		001	INSP			3498:30	07.04.2021	2221:12			36MO		5MO	07.04.2024	07 Apr 2024	142DY
ARC Extension		002	INSP			3498:30	07.04.2023	3156:36			12MO		5MO	07.04.2024	07 Apr 2024	142DY
Fire Extinguisher		007	INSP			3498:30	28.03.2023	3154:48			12MO		4MO	28.03.2024	28 Mar 2024	132DY
First Aid Kit		008	INSP			3498:30	28.03.2023	3154:48			12MO	15DY	5MO*	12.04.2024*	28 Mar 2024+15DY*	147DY
Perform Weight & Balance (AMC1 CAT.POL.MAB.100(b)) and replace POH W&B Report & Equipmentlist		009	INSP			3498:30	04.12.2019				48MO	30DY	47DY*	03.01.2024*	04 Dec 2023+30DY*	47DY
Austrian Requirements		010				3498:30										
LTH 40A 4.1 - Avionic Inspection		011	INSP			3498:30	31.03.2023	3154:48			24MO	30DY	17MO*	30.04.2025*	31 Mar 2025+30DY*	530DY
LTH 40A 4.2 - Transponder Inspection		012	INSP			3498:30	31.03.2023	3154:48			24MO	30DY	17MO*	30.04.2025*	31 Mar 2025+30DY*	530DY
LTH 40A 4.3 - Pitot Static Check		013	INSP			3498:30	31.03.2023	3154:48			24MO	30DY	17MO*	30.04.2025*	31 Mar 2025+30DY*	530DY
LTH 40A 4.3 - Compass Compensation		013	INSP			3498:30	28.03.2022	2702:00			24MO	30DY	5MO*	15.04.2024*	16 Mar 2024+30DY*	150DY
Scheduled Maintenance Airframe		100	INSP			3498:30										
RHC § 2.600 - 2200-hour inspection (R44 / R44 II)		101	INSP			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
RHC § 2.600 - 12-Year inspection		102	INSP			3498:30	04.12.2019	2062:30			144MO		97MO	04.12.2031	04 Dec 2031	2939DY
RHC § 2.400 - 100-hour/Annual Airframe Inspection		103	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC § 2.300 - Airframe Preparation for 100-Hour/Annual Inspection		103b	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC § 2.200 - Ground & Flight Check for 100hour/Annual Inspection		104	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC § 7.210 - Perform clutch assembly lubricant inspection & servicing		105	INSP			3498:30	26.09.2022	3069:42			500FH	25FH	87FH*	3585:30FH*	3560:30+25FH*	87FH
RHC § 1.120 - Drain and flush MGB		108	INSP			3498:30	26.09.2022	3069:42	4FH		500FH	25FH	87FH*	3585:30FH*	3560:30+25FH*	87FH
RHC § 1.130 - Drain and flush TGB		109	INSP			3498:30	26.09.2022	3069:42	4FH		500FH	25FH	87FH*	3585:30FH*	3560:30+25FH*	87FH
RHC § 1.115 - Clean gearbox chip detectors		110	INSP			3498:30	28.03.2023	3154:48	4FH		500FH / 12MO	25FH/15D Y	181:18FH*/5M O*	3679:48FH*/12.04.2024*	3654:48+25FH* / 28 Mar 2024+15DY*	181:18FH / 147DY
RHC § 1.140 - Lubricate C181-3 bearings		111	INSP			3498:30	01.10.2023	3456:12			300FH / 36MO	15FH/30D Y	271:18FH*/35 MO*	3769:48FH*/31.10.2026*	3754:48+15FH* / 01 Oct 2026+30DY*	271:18FH / 1079DY
RHC § 1.140 - Perform Ground Run after bearing lubrication		112	INSP			3498:30	01.10.2023	3456:12			300FH / 36MO	15FH/30D Y	271:18FH*/35 MO*	3769:48FH*/31.10.2026*	3754:48+15FH* / 01 Oct 2026+30DY*	271:18FH / 1079DY
RHC § 1.170 - Replace hydraulic filter		113	INSP			3498:30	01.10.2023	3456:12			300FH	15FH	271:18FH*	3769:48FH*	3754:48+15FH*	271:18FH
RHC SL-38 - Cracked MS2142L-Nuts Inspection		122	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC SL-43 - C343-1 Rev. L and prior Push-Pull Tube Inspection		123	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC SL-46 - Clean Air Filter P/N B771-1/B771-2		124	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC SL-46 - Air Filter Replacement P/N B771-1/B771-2		125	INSP			3498:30	18.06.2023	3262:30			600FH / 60MO	30FH/30D Y	394FH*/56MO*	3892:30FH*/18.07.2028*	3862:30+30FH* / 18 Jun 2028+30DY*	394FH / 1705DY
RHC SL-50 - D210 Corrosion-Resistant (CRES) Nuts		126	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
RHC SL-64A - Fire Extinguisher Handling & Maintenance P/N B381-(RT-A400)		127	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO: 1436:00	
Hobbs: 3498:30	Pn: O-540-F1B5	
Type: R44	Sn: L-26640-40A	
Sn: 1692		

Description	AD/SB/Mod	ATA / 1	Action	Pn	Sn	Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
RHC § 28-60 (RHC SL-70) - Main Rotor Blade Tip Maintenance		128	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
GTR225A Radio Inspection acc. GAMA Minor Change ICA-GTR225(x)		130	INSP	011-02807-0 0	2A601283 7	3498:30	28.03.2023	3154:48			12MO	15DY	5MO*	12.04.2024*	28 Mar 2024+15DY*	147DY
ELT Security (FAA SAIB AIR-22-03)	R44_SL-81	131	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
Tail Rotor Blade Condition and Care	R44_SL-82A	132	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
Perform EASA SIB No.: 2013-04R1 - Hook and Loop Style Fasteners as Mounting Mechanism for an Emergency Locator Transmitter	EASA_SIB_2 013-04R1; KANNAD_SB _S1800000-2 5	133	INSP			3498:30	28.03.2023	3154:48			12MO	15DY	5MO*	12.04.2024*	28 Mar 2024+15DY*	147DY
Tail Rotor Blade Inspection C029-3	R44_SB-112 _PART-A	134	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
Critical Tasks: The Maintenance Organization has to follow the manufacturer instructions and regulations acc. Part-M/ML and Part-145.		150	INSP			3498:30	01.10.2023	3456:12			100FH / 12MO	10FH/15D Y	66:18FH*/11M O*	3564:48FH*/16.10.2024*	3554:48+10FH* / 01 Oct 2024+15DY*	66:18FH / 334DY
Kannad AF-Compact - 6 Years Inspection (together with Battery replacement) acc. Kannad SL S1840501-25-05, current revision		186	INSP			3498:30	31.07.2023	3154:48			72MO		68MO	31.07.2029	31 Jul 2029	2083DY
Kannad AF-Compact - Annual Inspection acc. Kannad SL S1840501-25-05, current revision		187	INSP			3498:30	28.03.2023	3154:48			12MO	15DY	5MO*	12.04.2024*	28 Mar 2024+15DY*	147DY
Scheduled Engine Engine		200	INSP			3498:30										
LYC § 04.4 - 50-Hour Inspection		204	INSP			3498:30	01.10.2023	3456:12			50FH	5FH	11:18FH*	3509:48FH*	3504:48+5FH*	11:18FH
LYC § 04.5 - 100-Hour Inspection		205	INSP			3498:30	01.10.2023	3456:12			100FH	10FH	66:18FH*	3564:48FH*	3554:48+10FH*	66:18FH
LYC § 04.6 - 400-Hour Inspection (Shorter Intervall)		206	INSP			3498:30	30.07.2023	3360:06	100FH	300FH	30FH	191:36FH*	3690:06FH*	3660:06+30FH*	191:36FH	
LYC SI-1129D - Method of checking DC Alternator Belt Tension		207	INSP			3498:30	01.10.2023	3456:12			100FH	10FH	66:18FH*	3564:48FH*	3554:48+10FH*	66:18FH
LYC SI-1191A - Cylinder Compression		208	INSP			3498:30	01.10.2023	3456:12			100FH	10FH	66:18FH*	3564:48FH*	3554:48+10FH*	66:18FH
LYC SI-1080C - Maintenance Items for special attention		209	INSP			3498:30	01.10.2023	3456:12			50FH	5FH	11:18FH*	3509:48FH*	3504:48+5FH*	11:18FH
LYC SB-301C - Maintenance Procedure and Service Limitation for Valves		210	INSP			3498:30	30.07.2023	3360:06	100FH	300FH	30FH	191:36FH*	3690:06FH*	3660:06+30FH*	191:36FH	
LYC SB-366C - Carburetor Throttle Body Screw Inspection		212	INSP			3498:30	01.10.2023	3456:12			50FH / 12MO	5FH	11:18FH*/11M O	3509:48FH*/01.10.2024*	3504:48+5FH* / 01 Oct 2024	11:18FH / 319DY
LYC SB-388C / EU-2005-0023 R3 / LTA HB-2006-330 - Procedure to Determine Exhaust Valve and Guide Condition	EU-2005-002 3R3; LYC_SB-388 C	213	INSP			3498:30	30.07.2023	3353:42	100FH	330FH			185:12FH	3683:42FH	3683:42FH	185:12FH
Perform LYC SB-480F - (and R44 SL-83, as applicable) I. Oil & Filter Change & Screen Cleaning / II. Oil Filter/Screen Content Inspection. NOTE: Oil filters on D723-1 adapters do not require safety wire.	LYC_MSB-48 0F	215	INSP			3498:30	01.10.2023	3456:12	25FH	50FH / 4MO	5FH	11:18FH*/3MO	3509:48FH*/01.02.2024*	3504:48+5FH* / 01 Feb 2024	11:18FH / 76DY	
LYC SB-183A - Magneto Timing Discrepancies		216	INSP			3498:30	01.10.2023	3456:12			100FH	10FH	66:18FH*	3564:48FH*	3554:48+10FH*	66:18FH
Scheduled Maintenance LH Magneto		250	INSP			3498:30										
CMI SB-643C - LH Magneto 100 Hours		252	INSP	10-600616-3	E09AA039	3498:30	01.10.2023	3456:12			100±10FH		55:12FH	3553:42FH	3553:42±10FH	55:12±10FH
CMI SB-643C - LH Magneto 500 Hours		254	INSP	10-600616-3	E09AA039	3498:30	04.08.2023	3353:42			500FH / 48MO	25FH/30D Y	380:12FH*/46 MO*	3878:42FH*/03.09.2027*	3853:42+25FH* / 04 Aug 2027+30DY*	380:12FH / 1386DY
Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - LH Magneto		262	INSP			3498:30	04.08.2023	3353:42			500FH / 48MO	25FH/30D Y	380:12FH*/46 MO*	3878:42FH*/03.09.2027*	3853:42+25FH* / 04 Aug 2027+30DY*	380:12FH / 1386DY
Scheduled Maintenance RH Magneto		280				3498:30										

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO:	1436:00
Hobbs: 3498:30	Pn:	O-540-F1B5
Type: R44	Sn:	L-26640-40A
Sn: 1692		

Description	AD/SB/MOD	NATA / 1	Action	Pn	Sn	Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
CMI SB-643C - RH Magneto 100 Hours	282	INSP	10-600646-201	E11EA095		3498:30	01.10.2023	3456:12			100FH	10FH	65:12FH*	3563:42FH*	3553:42+10FH*	65:12FH
CMI SB-643C - RH Magneto 500 Hours	284	INSP	10-600646-201	E11EA095		3498:30	04.08.2023	3353:42			500FH / 48MO	25FH/30D Y	380:12FH*/46 MO*	3878:42FH*/03.09.2027*	3853:42+25FH* / 04 Aug 2027+30DY*	380:12FH / 1386DY
CMI SB-663A Two-Wire Magneto Tach. Breaker Contact (Points) Assy. P/N 10-400507 - RH Magneto Model S4LSC-204T (P/N 10-600644-201, BL-600644-201) and S6LSC-204T (P/N 10-600646-201, BL-600646-201)	288	INSP	10-600646-201	E11EA095		3498:30	04.08.2023	3353:42			500FH / 48MO	25FH/30D Y	380:12FH*/46 MO*	3878:42FH*/03.09.2027*	3853:42+25FH* / 04 Aug 2027+30DY*	380:12FH / 1386DY
Verify magneto (or EIS) drive cushion pliability (must tolerate 180° bend) - RH Magneto	292	INSP				3498:30	04.08.2023	3353:42			500FH / 48MO	25FH/30D Y	380:12FH*/46 MO*	3878:42FH*/03.09.2027*	3853:42+25FH* / 04 Aug 2027+30DY*	380:12FH / 1386DY
Fatigue Life Limited Parts/Overhaul/Additional Component Maintenance	300	LL				3498:30										
Main Rotor Blade	306	LL	C016-7	10714 REV.AJ		3498:30	18.01.2019	1995:06			2200FH / 144MO		696:36FH/86MO	4195:06FH/18.01.2031	4195:06FH / 18 Jan 2031	696:36FH / 2619DY
Main Rotor Blade	307	LL	C016-7	10716 REV.AJ		3498:30	18.01.2019	1995:06			2200FH / 144MO		696:36FH/86MO	4195:06FH/18.01.2031	4195:06FH / 18 Jan 2031	696:36FH / 2619DY
Upper Frame	308	LL	C020-1	10030		3498:30		2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Tail Rotor Blade	314	LL	C029-3	3764 REV.O		3498:30	17.10.2014	3154:48			2200FH / 144MO		1206:36FH/35 MO	4705:06FH/17.10.2026	4705:06FH / 17 Oct 2026	1206:36FH / 1065DY
Tail Rotor Blade	315	LL	C029-3	3766 REV.O		3498:30	17.10.2014	3154:48			2200FH / 144MO		1206:36FH/35 MO	4705:06FH/17.10.2026	4705:06FH / 17 Oct 2026	1206:36FH / 1065DY
Pinion, Main Gearbox	320	LL	C146-2	R0383 REV.O		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Main Rotor Hub	321	LL	C154-1	11230		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Main Rotor Spindle	322	LL	C158-1	24370		3498:30	10.04.2009	1995:06			2200FH		696:36FH	4195:06FH	4195:06FH	696:36FH
Main Rotor Spindle	323	LL	C158-1	24372		3498:30	10.04.2019	1995:06			2200FH		696:36FH	4195:06FH	4195:06FH	696:36FH
Sump, Main Gearbox	326	LL	C263-2	8011 REV.H		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Housing, Main Gearbox	328	LL	C264-2	10465 REV.L		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Pinion, Tail Gearbox	330	LL	C545-2	11740 REV.J		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Bearing Set, C017-6 Swashplate	331	LL	C647-12	G181933 REV.AC		3498:30	28.03.2022	2702:00			2200FH		1105FH	4603:30FH	4603:30FH	1105FH
Tail Rotor Guard	333	LL	D079-1	0805		3498:30	06.07.1999	2199:00			2200FH		900:30FH	4399FH	4399FH	900:30FH
Tail Rotor Hub	334	LL	G062-2	2639 REV.E		3498:30	21.03.2023	3154:48			2200FH		1206:36FH	4705:06FH	4705:06FH	1206:36FH
Tailcone Assembly, Rev N & Subsequ.	336	LL	C023-1	3846		3498:30	05.02.2007	0:00			4400FH		901:30FH	4400FH	4400FH	901:30FH
Horizontal Stabilizer, Rev. M & Subsequ.	342	LL	C044-1	5796 REV.V		3498:30	17.08.2022	2964:00			4400FH		1684:54FH	5183:24FH	5183:24FH	1684:54FH
Lower Swashplate	344	LL	C198-2	3363 REV.M		3498:30	04.12.2019	2062:30			4400FH		1376:12FH	4874:42FH	4874:42FH	1376:12FH
Main Rotor Shaft	345	LL	C251-1	R4384 REV.N		3498:30	04.12.2019	2062:30			4400FH		2964FH	6462:30FH	6462:30FH	2964FH
Tail Rotor Drive Shaft	349	LL	D196-1	1915		3498:30	05.02.2007	0:00			4400FH		901:30FH	4400FH	4400FH	901:30FH
Tail Rotor Bellcrank	350	TBO	A120-3			3498:30	22.05.2019	2062:30			144MO		90MO	22.05.2031	22 May 2031	2743DY
Tail Rotor Bellcrank	351	OTL	A120-3			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
V-belts	352	TBO	A190-3			3498:30	22.05.2019	2062:30			144MO		90MO	22.05.2031	22 May 2031	2743DY
V-belts	353	OTL	A190-3			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO: 1436:00	
Hobbs: 3498:30	Pn: O-540-F1B5	
Type: R44	Sn: L-26640-40A	
Sn: 1692		

Description	AD/SB/MOD	ATA / 1	Action Pn	Sn		Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
Battery cables	356	OTL	A780-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Hoses, Air Ducts	358	TBO	A785-x			3498:30	22.05.2019				144MO		90MO	22.05.2031	22 May 2031	2743DY
Hoses, Air Ducts	359	OTL	A785-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Flex Plate Assy	362	OTL	A947-2			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Alternator Belt	363	TBO	B173-x			3498:30	22.05.2019	2062:30			144MO		90MO	22.05.2031	22 May 2031	2743DY
Alternator Belt	364	OTL	B173-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Hoses Assys	365	TBO	B283-x			3498:30	22.05.2019				144MO		90MO	22.05.2031	22 May 2031	2743DY
Hoses Assys	366	OTL	B283-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Main Rotor Blade and Spindle Assy	369	TBO	C005-12			3498:30	10.04.2019	1995:06			2200FH		696:36FH	4195:06FH	4195:06FH	696:36FH
Main Rotor Blade and Spindle Assy	370	INSP	C005-12			3498:30	04.12.2019	1995:06			144MO		97MO	04.12.2031	04 Dec 2031	2939DY
Main Rotor Hub Assy	371	INSP	C005-x			3498:30	04.12.2019				144MO		97MO	04.12.2031	04 Dec 2031	2939DY
Main Rotor Gearbox and Mast Assy	372	TBO	C006-8	1094 REV.AL		3498:30		2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Main Rotor Gearbox and Mast Assy	373	INSP	C006-8	1094 REV.AL		3498:30	13.05.2019	2062:30			144MO		90MO	13.05.2031	13 May 2031	2734DY
Fanshaft and Bearing Assy	374	TBO	C007-5			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Fanshaft and Bearing Assy	375	INSP	C007-5			3498:30	13.08.2019	2062:30			144MO		93MO	13.08.2031	13 Aug 2031	2826DY
Tail Rotor Assy	376	TBO	C008-9			3498:30	21.03.2023	3154:48			2200FH		1206:36FH	4705:06FH	4705:06FH	1206:36FH
Tail Rotor Assy	377	INSP	C008-9			3498:30	17.10.2014	3154:48			144MO		35MO	17.10.2026	17 Oct 2026	1065DY
Swashplate Assy	379	TBO	C017-6	2737 REV.AE		3498:30	28.03.2022	2702:00			2200FH		1105FH	4603:30FH	4603:30FH	1105FH
Swashplate Assy	380	INSP	C017-6	2737 REV.AE		3498:30	23.03.2019	2702:00			144MO		88MO	23.03.2031	23 Mar 2031	2683DY
Clutch Assy	381	TBO	C018-2			3498:30	04.12.2019	2062:30			2200FH		488FH	3986:30FH	3986:30FH	488FH
Clutch Assy	382	INSP	C018-x			3498:30	02.08.2016	2062:30			144MO		57MO	02.08.2028	02 Aug 2028	1720DY
Tail Rotor Gearbox Assy	383	TBO	C021-1	2466 REV.J		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Tail Rotor Gearbox Assy	384	INSP	C021-1	2466 REV.J		3498:30	20.05.2019	2062:30			144MO		90MO	20.05.2031	20 May 2031	2741DY
Tail Rotor Pitch Control	386	TBO	C031-1	11723		3498:30	22.04.2019	2062:30			2200FH / 144MO		764FH/89MO	4262:30FH/22.04.2031	4262:30FH / 22 Apr 2031	764FH / 2713DY
Bearing Assy	387	TBO	C041-11	0901		3498:30	05.06.2018	2062:30			144MO		79MO	05.06.2030	05 Jun 2030	2392DY
Belt Tension Actuator Assy	388	TBO	C051-1	7681 REV.W		3498:30	04.12.2019	2062:30			2200FH		655:18FH	4153:48FH	4153:48FH	655:18FH
Belt Tension Actuator Assy	389	INSP	C051-1	7681 REV.W		3498:30	11.02.2016	2062:30			144MO		51MO	11.02.2028	11 Feb 2028	1547DY
Tail Rotor Push-Pull Tube Assy	391	OTL	C121-17			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Muffler with Risers	392	OTL	C169-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Main Rotor Pitch Link Assy	393	OTL	C258-1			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Swashplate Boot	394	TBO	C480-1			3498:30	22.05.2019	2062:30			144MO		90MO	22.05.2031	22 May 2031	2743DY
Swashplate Boot	395	OTL	C480-1			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO: 1436:00	
Hobbs: 3498:30	Pn: O-540-F1B5	
Type: R44	Sn: L-26640-40A	
Sn: 1692		

Description	AD/SB/MOD	ATA / 1	Action Pn	Sn		Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
Harness & Buckle Assy	399	TBO	C628-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Harness & Buckle Assy	400	TBO	C628-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Harness & Buckle Assy	401	TBO	C628-x			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Mount	402	TBO	C653-1			3498:30	23.05.2019	2062:30			144MO		90MO	23.05.2031	23 May 2031	2744DY
Mount	403	TBO	C653-2			3498:30	23.05.2019	2062:30			144MO		90MO	23.05.2031	23 May 2031	2744DY
Dual Tachometer	405	TBO	C792-5	L21-10191		3498:30	01.07.2022	3069:42			2200FH		1771:12FH/12 8MO	5269:42FH/01.07.2034	5269:42FH / 01 Jul 2034	1771:12FH / 3879DY
Flex Plate Assy	407	OTL	C947-1			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Flex Plate Assy	408	OTL	C947-3	REV.G		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Fanwheel Assy	409	TBO	D174-2	REV.O		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Fanwheel Assy	410	INSP	D174-2	REV.O		3498:30	20.05.2019	2062:30			144MO		90MO	20.05.2031	20 May 2031	2741DY
Hydraulic Reservoir	411	TBO	D211-1	3679 REV.J		3498:30	21.03.2023	3154:48			2200FH		1856:18FH	5354:48FH	5354:48FH	1856:18FH
Hydraulic Reservoir	412	INSP	D211-1	5090		3498:30	25.06.2012	2062:30			144MO		7MO	25.06.2024	25 Jun 2024	221DY
Hydraulic Servo Actuators	413	TBO	D212-1	5963 REV.G		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Hydraulic Servo Actuators	413	TBO	D212-1	2270 REV.F		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Hydraulic Servo Actuators	413	TBO	D212-	9220 REV.I		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Hydraulic Servo Actuators	414	INSP	D212-1	5963 REV.G		3498:30	19.07.2019	2062:30			144MO		92MO	19.07.2031	19 Jul 2031	2801DY
Hydraulic Servo Actuators	414	INSP	D121-1	9220 REV.I		3498:30	12.04.2019				144MO		89MO	12.04.2031	12 Apr 2031	2703DY
Hydraulic Servo Actuators	414	INSP	D212-1	2270 REV.F		3498:30	26.08.2019				144MO		93MO	26.08.2031	26 Aug 2031	2839DY
Governor Controller Assy	416	TBO	D278-1R	0609 REV.E		3498:30		2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Governor Controller Assy	417	INSP	D278-1R	0609		3498:30	08.05.2019	2062:30			144MO		90MO	08.05.2031	08 May 2031	2729DY
Bellcrank Assy	418	TBO	D756-3 / D756-4			3498:30	22.05.2019	2062:30			144MO		90MO	22.05.2031	22 May 2031	2743DY
Engine Cooling Panels (consult IPC)	419	OTL	Various			3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
Clutch Shaft	420	TBO	C166-4	9939 REV.P		3498:30	04.12.2019	2062:30			2200FH		488FH	3986:30FH	3986:30FH	488FH
Clutch Shaft	421	INSP	C166-4	9939 REV.P		3498:30	02.08.2016	2062:30			144MO		57MO	02.08.2028	02 Aug 2028	1720DY
Bearing Assy	422	TBO	C181-3	4009		3498:30		2062:30			2200FH		488FH	3986:30FH	3986:30FH	488FH
Bearing Assy	423	INSP	C181-3	4009		3498:30	13.08.2019	2062:30			144MO		93MO	13.08.2031	13 Aug 2031	2826DY
Sprag Clutch	424	TBO	C188-3	10694 REV.H		3498:30	04.12.2019	2062:30			2200FH		488FH	3986:30FH	3986:30FH	488FH
Sprag Clutch	425	INSP	C188-3	10694 REV.H		3498:30	02.08.2016	2062:30			144MO		57MO	02.08.2028	02 Aug 2028	1720DY
Hydraulic Pump	426	TBO	D500-1	5345 REV.I		3498:30	04.12.2019	2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH
RHC § 1.102 A. Perform 12 Years Additional Component Maintenance	500					3498:30	04.12.2019				144MO		97MO	04.12.2031	04 Dec 2031	2939DY
RHC § 1.102 B. Perform 2200/2400 Hours Additional Component Maintenance	510					3498:30		2062:30			2200FH		764FH	4262:30FH	4262:30FH	764FH

OE-XXZ - Recurring Maintenance (All)

Aircraft	Engine(s)	1
TT: 3498:30	TSO: 1436:00	
Hobbs: 3498:30	Pn: O-540-F1B5	
Type: R44	Sn: L-26640-40A	
Sn: 1692		

Description	AD/SB/MOD	ATA / 1	Action	Pn	Sn		Curr. FH	Start date	Ac. TT	LSV	TH	Int.	Ext.*	Rem.	Due	Due RT	Rem. RT
Engine Overhaul							3498:30										
Engine							3498:30	06.09.2019	2062:30			2000FH / 144MO	200FH	764FH*/94MO	4262:30FH*/06.09.2031	4062:30+200FH* / 06 Sep 2031	764FH / 2850DY
Magneto LH							3498:30	28.07.2023	3353:42			2000FH / 144MO	200FH	2055:12FH*/14 OMO	5553:42FH*/28.07.2035	5353:42+200FH* / 28 Jul 2035	2055:12FH / 4271DY
Magneto RH							3498:30	23.07.2023	3353:42			2000FH / 144MO	200FH	2055:12FH*/14 OMO	5553:42FH*/23.07.2035	5353:42+200FH* / 23 Jul 2035	2055:12FH / 4266DY
Carburetor							3498:30	06.09.2019	2062:30			2000FH	200FH	764FH*	4262:30FH*	4062:30+200FH*	764FH
Starter							3498:30	06.09.2019	2062:30			2000FH	200FH	764FH*	4262:30FH*	4062:30+200FH*	764FH
Alternator							3498:30	05.04.2019	2062:30			2000FH	200FH	764FH*	4262:30FH*	4062:30+200FH*	764FH
Oil Cooler							3498:30	29.08.2019	2062:30			2200FH / 144MO		764FH/93MO	4262:30FH/29.08.2031	4262:30FH / 29 Aug 2031	764FH / 2842DY
Additional Requirements							3498:30										
ELT Battery							3498:30	31.07.2023	3154:48			72MO		68MO	31.07.2029	31 Jul 2029	2083DY
Fire Extinguisher							3498:30	31.12.2017				144MO		73MO	31.12.2029	31 Dec 2029	2236DY
First Aid Kit							3498:30	30.09.2019	3456:12			60MO		10MO	30.09.2024	30 Sep 2024	318DY
Check that current POH Revision is installed							3498:30	21.03.2023	3154:48			12MO	15DY	5MO*	05.04.2024*	21 Mar 2024+15DY*	140DY
Check that current Pilot Checklist is installed							3498:30	21.03.2023	3154:48			12MO	15DY	5MO*	05.04.2024*	21 Mar 2024+15DY*	140DY