

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description	PART						AC		REMOVAL				
	Part No.	Serial No.	Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
<b>AIRCRAFT COMPONENTS</b>													
<b>MR Assy.</b>		OC		AC Hours				0,0 h	9-Feb-2007				
C005-8		OC		Years				0,0 h					
<b>MR Blade Assy.</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C016-5	3198 Rev. Y	SLL	12	Years						9-Feb-2019		93 D	
<b>MR Blade Assy.</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C016-5	3434 Rev. Y	SLL	12	Years						9-Feb-2019		93 D	
<b>MR Spindle</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C158-1	7710 Rev. I	TBO	12	Years						9-Feb-2019		93 D	
<b>MR Spindle</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C158-1	7712 Rev. I	TBO	12	Years						9-Feb-2019		93 D	
<b>MR Hub Assy.</b>		OC		AC Hours				0,0 h	9-Feb-2007				
C005-4		OC		Years									
<b>MR Hub</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C154-1	3779 Rev. E	SC	12	Years						9-Feb-2019		93 D	
<b>MR Swashplate</b>		TBO	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C017-4	3614 Rev. Y	TBO	12	Years						9-Feb-2019		93 D	
<b>Lower Swashplate</b>		SLL	4.400	AC Hours				0,0 h	9-Feb-2007	4.400,0 h		2.431,3 h	
C198-2	3877 Rev. M												
<b>MR Gearbox</b>		TBO	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C006-5	3961 Rev AB	TBO	12	Years						9-Feb-2019		93 D	
<b>MR Gearbox Sump</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C263-2	1403 Rev. G	TBO	12	Years						9-Feb-2019		93 D	
<b>MR Gearset</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C146-5	3922 Rev. L	TBO	12	Years						9-Feb-2019		93 D	
<b>MR Gearbox Housing</b>		SLL	2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C264-1	3961 Rev. I	TBO	12	Years						9-Feb-2019		93 D	

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description		PART					AC		REMOVAL			
		Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
Part No.	Serial No.											
<b>MR Driveshaft</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C251-2	R4610 Rev. N	TBO	12	Years					9-Feb-2019		93 D	
<b>Clutch Assy.</b>		OC		AC Hours			1.648,1 h	11-Nov-2015				
C018-2		OC		Years								
<b>Clutch Shaft</b>		TBO	2.200	AC Hours			1.648,1 h	11-Nov-2015	2.200,0 h		231,3 h	
C166-4	9647 Rev. S	TBO	12	Years					11-Nov-2027		3290 D	
<b>Sprag Clutch</b>		TBO	2.200	AC Hours			1.648,1 h	11-Nov-2015	2.200,0 h		231,3 h	
C188-3	10411 Rev. S	TBO	12	Years					11-Nov-2027		3290 D	
<b>Clutch Actuator Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C051-2	3766 Rev. U	TBO	12	Years					9-Feb-2019		93 D	
<b>Hydraulic Servo Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D212-1	8225 Rev. I	TBO	12	Years					9-Feb-2019		93 D	
<b>Hydraulic Servo Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D212-1	8232 Rev. I	TBO	12	Years					9-Feb-2019		93 D	
<b>Hydraulic Servo Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D212-1	8233 Rev. I	TBO	12	Years					9-Feb-2019		93 D	
<b>Hydraulic Reservoir, 28V</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D211-2	2750 Rev. J	TBO	12	Years					9-Feb-2019		93 D	
<b>Hydraulic Pump Assy.</b>		TBO	2.200	AC Hours			1.524,0 h	10-Jul-2015	2.200,0 h		231,3 h	
D500-1	4641	TBO	12	Years					10-Jul-2027		3166 D	
<b>Frame Assy. Upper</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C020-1	3737 Rev. U	SC	12	Years					9-Feb-2019		93 D	
<b>Fan Shaft, Bearing &amp; Housing Assy.</b>		OC		AC Hours			0,0 h	9-Feb-2007				
C007-5												
<b>Bearing Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C181-3	4038 Rev. H	TBO	12	Years					9-Feb-2019		93 D	

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description		PART					AC		REMOVAL			
		Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
Part No.	Serial No.											
<b>Fanwheel Assy.</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D174-2		TBO	12	Years					9-Feb-2019		93 D	
<b>Tailcone Assy.</b>		SLL	4.400	AC Hours			0,0 h	9-Feb-2007	4.400,0 h		2.431,3 h	
C023-1	3902 Rev. AH											
<b>TR Driveshaft</b>		SLL	4.400	AC Hours			0,0 h	9-Feb-2007	4.400,0 h		2.431,3 h	
D196-1	1868 Rev. C											
<b>TR Gearbox</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C021-1	3557 Rev. K	TBO	12	Years					9-Feb-2019		93 D	
<b>TR Gearset</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C545-1	4168 Rev. H	TBO	12	Years					9-Feb-2019		93 D	
<b>TR Assy.</b>		OC		AC Hours			0,0 h	9-Feb-2007				
C008-4												
<b>TR Blade</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C029-2	4604 Rev. L	SLL	12	Years					9-Feb-2019		93 D	
<b>TR Blade</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C029-2	4600 Rev. L	SLL	12	Years					9-Feb-2019		93 D	
<b>TR Hub Assy.</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D062-2	3212 Rev. C											
<b>TR Pitch Control</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
C031-1	3988 Rev. J	TBO	12	Years					9-Feb-2019		93 D	
<b>Horizontal Stabilizer</b>		SLL	4.400	AC Hours			0,0 h	9-Feb-2007	4.400,0 h		2.431,3 h	
C044-1	3723 Rev. T											
<b>TR Guard Assy.</b>		SLL	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D079-1	4023 Rev. T											
<b>Governor Controller</b>		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
D278-2	1695 Rev. E	TBO	12	Years					9-Feb-2019		93 D	

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description		PART					AC		REMOVAL			
		Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
Part No.	Serial No.											
<b>Seat Belt, Fwd. LH</b> C628-1		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
<b>Seat Belt, Fwd.RH</b> C628-2		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
<b>Seat Belt , Aft.</b> C628-3		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
<b>Seat Belt , Aft.</b> C628-3		TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
<b>A/C Battery, 28V</b> RG24-15	40773678	OC		Years			0,0 h	21-Jul-2017				
<b>Fire Extinguisher, Total</b> 74-00		OTL	10	Years			0,0 h					
<b>ENGINE COMPONENTS</b>												
<b>Engine, Lycoming</b> IO-540-AE1A5	L-31739-48A	TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
		TBO	12	Years		153,0 D			9-Sep-2018		-60 D	
<b>Magneto, LH</b> Bendix/TCM Aircraft Products Div. 10-600616-9	E08JA061	TBO	2.200	AC Hours			1.887,3 h	25-Mar-2017	2.200,0 h		231,3 h	
		TBO	12	Years					25-Mar-2029		3790 D	
<b>Magneto, RH</b> Bendix/TCM Aircraft Products Div. 10-600646-201	E08JA027	TBO	2.200	AC Hours			1.887,3 h	25-Mar-2017	2.200,0 h		231,3 h	
		TBO	12	Years					25-Mar-2029		3790 D	
<b>Fuel Control</b> Precision Airmotiv 2576630-4	70BF6806	TBO	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
<b>Oil Cooler, large</b> Stewart Warner	C649-2 3162	SC	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
		SC	12	Years					9-Feb-2019		93 D	

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description		PART					AC		REMOVAL			
		Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
Part No.	Serial No.											
<b>Oil Cooler, small</b>		SC	2.200	AC Hours			0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
Stewart Warner	C649-1 657											
<b>Starter, 28V</b>		TBO	2.200	AC Hours			531,8 h	18-Aug-2011	2.731,8 h		763,1 h	
B&C Specialty Products												
BC315-100-4	908240951											
<b>Alternator, 28V-70A</b>		TBO	2.200	AC Hours			304,7 h	8-May-2009	2.504,7 h		536,0 h	
Hartzell Engine Technologies												
ALU-8521-LS	I113167											
<b>AIRCRAFT EQUIPMENT</b>												
<b>Airspeed Indicator</b>		OC		AC Hours			0,0 h	9-Feb-2007				
United Instruments	8000 194340	OC		Years								
<b>Altimeter, mbar</b>		OC		AC Hours			0,0 h	9-Feb-2007				
United Instruments	5934PM-3 455360	OC		Years								
<b>Attitude Gyro</b>		OC		AC Hours			0,0 h	9-Feb-2007				
BF Goodrich	1100-14S 25577	OC										
<b>Vertical Card Compass</b>		OC		AC Hours			0,0 h	9-Feb-2007				
Precision Aviation	PAI-700 60435	OC		Years								
<b>Instrument Cluster Assy., 28V</b>		OC		AC Hours			0,0 h	9-Feb-2007				
Rochester	B144-4 1655	OC		Years								

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description	PART						AC		REMOVAL				
	Part No.	Serial No.	Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
<b>Manifold Pressure Gauge</b>				AC Hours				0,0 h	9-Feb-2007				
United Instruments 6111	192331												
<b>OAT Gauge</b>				AC Hours				0,0 h	9-Feb-2007				
Davtron 307 FC	A10712												
<b>Dual Tachometer (101-102%)</b>			2.200	AC Hours				0,0 h	9-Feb-2007	2.200,0 h		231,3 h	
Phaostron C792-4	3398		12	Years						9-Feb-2019		93 D	
<b>Vertical Speed Indicator</b>				AC Hours				0,0 h	9-Feb-2007				
United Instruments 7000	361645			Years									
<b>Chronometer, 14V</b>				AC Hours				0,0 h	9-Feb-2007				
Astrotech LC-2				Years									
<b>Indicator</b>				AC Hours				0,0 h	21-Aug-2007				
Garmin G1 106A	A21269			Years									
<b>Radar Altimeter</b>				AC Hours				0,0 h	9-Feb-2007				
Free Flight TR3500	6293117			Years									
<b>Radar Indicator</b>				AC Hours				0,0 h	9-Feb-2007				
Free Flight TRI 40	6332115			Years									
<b>Turn Coordinator</b>				AC Hours				0,0 h	9-Feb-2007				
1394T100-7Z	D06-11586			Years									
<b>Directional Gyro</b>				AC Hours				0,0 h	9-Feb-2007				
BF Goodrich 205-1B	26026			Years									
<b>AVIONIK EQUIPMENT</b>													
<b>ELT 406MHz</b>				AC Hours				0,0 h	9-Feb-2007				
Kannad 406AF	2613735-0024			Years									
<b>ELT Battery, Kannad 406AF</b>			72	Month				0,0 h	22-Apr-2016	22-Apr-2022		1261 D	
S1820516-99													
<b>COM/NAV/GPS</b>				AC Hours				0,0 h	9-Feb-2007				
Garmin GNS 430	97137787			Years									

AC Type: **R44 II** AIRCRAFT  
 AC Serial No.: **11624** Hours: **1.968,7**  
 AC Year of MFG: **2007** Landings: **N/A**  
 Date of check: **8-Nov-2018**

Description		PART					AC		REMOVAL			
		Limit	Type of Limit	Tolerance	Consumed Time	Total Time	Hours at Installation	Date at Installation	due at	incl. Tolerance	Remaining Time	Remaining incl. Tol.
Part No.	Serial No.											
<b>Transponder</b>		OC	AC Hours				0,0 h	9-Feb-2007				
Garmin GTX330	8412475	OC	Years									
<b>Blind Encoder</b>		OC	AC Hours				0,0 h	9-Feb-2007				
Trans Cal SSD120-30A	A67090	OC	Years									
<b>Audio Control (single)</b>		OC	AC Hours				0,0 h	9-Feb-2007				
NAT AA12S-002	1764	OC	Years									